

GEOHAZARD ASSESSMENT PROGRAM
NORTH CENTRAL REGION – ATHABASCA
2012 INSPECTION



| Site Number | Location | Name | Hwy | km |
|-------------------|---------------------------------------|--|----------|------|
| NC 72 | 20 m east of south Mitsue access road | Graduation Rock Backslope Slump | 2:46 | 42.5 |
| Legal Description | | UTM Co-ordinates (NAD 83) | | |
| N.E.15-72-4-W5M | | 12 N 6124185 | E 656972 | |

| | Date | PF | CF | Total |
|-----------------------------|--|--------------|------|-------|
| Previous Inspection: | May 4, 2011 | 7 | 2 | 14 |
| Current Inspection: | June 11, 2012 | 7 | 2 | 14 |
| Road AADT: | 2560 | Year: | 2011 | |
| Inspected By: | Tarek Abdelaziz, Don Proudfoot (Thurber) Gordon Wolters, Roger Skirrow, Arthur Kavulok (TRANS) | | | |
| Report Attachments: | <input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items | | | |

| | | |
|--|--|--------------------------|
| Primary Site Issue: | EBL backslope slump material pushing into highway ditch and impeding drainage | |
| Dimensions: | 5- 8 m wide (parallel to highway) x 16 m long (parallel to slope surface) | |
| Date of any remediation: | N/A | |
| Maintenance: | Issue was first noticed in 2009 and the ditch has been maintained and cleared of the slump material in 2010 to enhance the drainage characteristics of the highway EBL ditch | |
| Observations: | Description | Worse? |
| <input type="checkbox"/> Pavement Distress | | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> Slope Movement | Up to 1.5 m high multiple scarps within the slump mass. The slump materials consist of fissured low to medium plastic clay and silty fine sand; slight retrogression of headscarp cracks | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> Erosion | Some erosion within the slump mass | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> Seepage | Dry catch water ditch in 2012; unimpeded surface water flow in the highway ditch | <input type="checkbox"/> |
| <input type="checkbox"/> Bridge/Culvert Distress | | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> Other | Vegetation has grown within the slump mass | <input type="checkbox"/> |

Instrumentation: None

Assessment (Refer to attached Figure 1):

It appears that the slump mass has moved a bit, as manifested from the slight retrogression of the headscarp cracks, however the site conditions did not change significantly from last year.

The vegetation growth should help increasing the overall stability of the slump mass. Erosion and transportation of sediments to the bottom of the slope may still occur, but at a slower rate than experienced in the past in the absence of vegetation cover.

Recommendations:

In the short term, the local MCI should continue to monitor the site and clean the ditch, as required, to maintain its drainage characteristics. If the slump materials start to accumulate in the ditch and block natural drainage, ground water levels may rise in the vicinity of the highway embankment and result in instability of the highway side slopes.


The recommended long-term remedial measure consists of excavating and replacing the slump mass with compacted granular fill. This option will also require constructing a longitudinal sub-drain along the base of the excavated mass and a riprap lined swale extending from the bush line to the bottom of the slope to drain the surface water from the catch water ditch in a controlled manner into the highway ditch. Ditch armouring using riprap along the bottom of the slope will also be required. The pall bark cost of this option would be in the range of \$75,000.

LEGEND


- ① → PHOTOGRAPH NUMBER, AND APPROXIMATE DIRECTION AND LOCATION (JUNE 11, 2012)
- ⊙ LIGHT POLE
- ▲ SCARP
- ~~~~~ BUSH LINE

NOTES:


1. THE DIMENSIONS SHOWN ON THE SITE PLAN AND CROSS-SECTION ARE BASED ON SIMPLE FIELD MEASUREMENTS AND MAY DEVIATE FROM THE ACTUAL CONDITION.
2. JUNE 11, 2012 SITE OBSERVATIONS ARE SHOWN IN RED.



SITE PLAN
SCALE - 1:500



CROSS-SECTION A-A'
SCALE - 1:250




**NORTH CENTRAL REGION (ATHABASCA AREA)
- 2012 GEOHAZARD ASSESSMENT**

**NC72: HWY 2:46 GRADUATION ROCK
BACKSLOPE SLUMP (km 42.5)
SITE PLAN AND CROSS - SECTION A-A'**

FIGURE NC72-1

| | |
|-------------|---------------|
| DRAWN BY | ML |
| DESIGNED BY | TSA |
| APPROVED BY | DWP |
| SCALE | AS SHOWN |
| DATE | NOVEMBER 2012 |
| FILE No. | 15-16-275 |



THURBER ENGINEERING LTD.



Photo# 1 General view of highway backslope slump; note that vegetation has grown within the slump mass (looking south)



Photo# 2 Highway surface and side slope at the slump location, looking east



Photo# 3 Looking east at the west facing crack; the exposed face of the crack consists of fine silty sand



Photo# 4 Looking east at the slump cracks near the crest of the slope; note further movement of headscarp cracks



Photo# 5 Looking northwest at the slump cracks near the crest of the slope; note the retrogression of the scarp cracks