

December 21, 2007

File: 15-85-66

Alberta Infrastructure and Transportation Unit 2, Jewell Building 3603 – 53 Street Athabasca, Alberta T9S-1A9

Attention:

Mr. Arthur Kavulok

NORTH CENTRAL REGION (ATHABASCA AREA) GEOHAZARD ASSESSMENT HWY 63:12 BACKSLOPE SLUMPS (NC 17C), NORTH OF FORT MCMURRAY 2007 ANNUAL INSPECTION REPORT

Dear Sir:

This letter documents the 2007 annual site inspection of an area of former slope instability located along Hwy 63:12 about 11.3 km north of Fort McMurray. The legal description of the site is SW7-91-9-W4M. Thurber Engineering Ltd. (Thurber) undertook this inspection in partial fulfillment of our Geotechnical Services for Geohazard Assessment, Instrumentation Monitoring and Related Work contract (CE143/2006) with Alberta Infrastructure and Transportation (INFTRA).

Mr. Don Proudfoot, P.Eng. of Thurber undertook the inspection on July 17, 2007 in the presence of Mr. Roger Skirrow, P. Eng., Mr. Arthur Kavulok and Mr. Ron Behr of INFTRA.

1. BACKGROUND

The geohazard consisted of two slides that had occurred in local high points of the highway backslope. The slides, which were spaced about 200 m apart, were called the North Slump and the South Slump. A major buried oil pipeline owned and operated by Enbridge Pipelines, which services Suncor, is located in a right-of-way (R/W) upslope of the two former slides.

Discussions with Mr. Behr indicate that in addition to the slide problem, ongoing seepage in the winter was causing ditch icing problems in this area.

Thurber last visited the site as part of the geohazard assessment program on May 12, 2006 and the site condition at that time is described in our Part B assessment letter in the site binder. Since that time Thurber carried out a geotechnical investigation and preliminary engineering assessment to determine the conditions leading to failure and potential preliminary remedial measures to mitigate the sliding conditions. The results of the investigation and assessment were presented in a report dated August 18, 2006.

Later in the year Thurber developed a detailed design for remediation of the slides and Prairie North Constr. Ltd constructed the remedial measures in early 2007. The remedial measures consisted of excavating the slide areas and rebuilding the backslope with granular fill. Gravel filled shear keys were incorporated below the toe areas of the rebuilt slopes. A gabion wall was constructed to retain the toe of the South Slump in order to provide sufficient width for the highway ditch. The slide areas and shear keys were excavated and backfilled in sections in order to reduce the risk of failure of the excavation cut slopes.

Subdrains were incorporated at the back of the granular fill in each slide area to intercept seepage and lower the ground water table in the slope. The highway ditch was also regraded to prevent ponding of water in uneven sections. Catchwater ditches were also constructed on the upslope side outside the pipeline R/W to intercept surface flow and train it into riprap-lined swales that drained into the highway ditch. Thurber prepared a construction summary report dated June 25, 2007, which describes the construction of the remedial measures. A copy of the as-built drawings is attached to this letter for inclusion in Section G of the site binder.

2. SITE OBSERVATIONS

Selected photographs of the site taken during our July 17, 2007 visit are attached to this letter. The construction of the remedial measures had already been completed and a good grass growth had already developed on the slopes, ditch and swales. There were no visible signs of distress in the slopes or erosion on site. The grass growth was somewhat retarded along the down slope side of the catchwater ditch due to ongoing all-terrain vehicle traffic through this area.

3. ASSESSMENT AND RECOMMENDATIONS

The recent remedial measures should correct the previous slide condition. The MCI should visually monitor the site a few times over the next year to confirm that there are no further signs of movements and that there are no locations of erosion forming in the newly graded swales, slopes and highway ditch. Due to the high consequence of failure at this location it is recommended that the site be included

Client: Alberta Infrastructure and Transportation

File: 15-85-66

e-file: 08\85-66 NC 17C

Date: December 21, 2007 Page 2 of 3



for a detailed visual assessment for one more year as part of the geohazard program.

CLOSURE

We trust this assessment and recommendations meet with your needs at this time. Please contact the undersigned should questions arise or if the conditions of the slides worsen.

Yours very truly, Thurber Engineering Ltd.

Don Proudfoot, P.Eng. Review Principal

/dw

Attachments

cc Mr. Roger Skirrow, P.Eng., Director of Geotechnical Services, AIT

Client:

Alberta Infrastructure and Transportation

File:

15-85-66

e-file: 08\85-66 NC 17C

Date: December 21, 2007

Page 3 of 3



Photo 1 - Repaired North Slump Area and swale.



Photo 2 - Repaired South Slump Area.




Photo 3 - Highway Ditch in Regraded Section.





Photo 4 - Catchwater Ditch and Shallow Berm at Top of Cleared Slope.





Photo 5 - Armoured Swale Between the Repaired Slump Areas.


































Photo 1 - Repaired North Slump Area and swale.



Photo 2 - Repaired South Slump Area.



Photo 3 - Highway Ditch in Regraded Section.



Photo 4 - Catchwater Ditch and Shallow Berm at Top of Cleared Slope.



Photo 5 - Armoured Swale Between the Repaired Slump Areas.