

**TRANSPORTATION AND ECONOMIC CORRIDORS
GEOHAZARD ASSESSMENT PROGRAM
NORTH CENTRAL REGION – ATHABASCA &
FORT McMURRAY DISTRICTS
2023 SITE INSPECTION**



Site Number	Location	Name		Hwy	km
NC006	11 Km East of Slave Lake	Mitsue Recreation Area		2:46	47.33
Legal Description		UTM Co-ordinates (NAD 83)			
NW-7-72-4-W5M		11	N	6122200	E 651552
	Date	PF	CF	Total	
Previous Inspection:	June 07, 2022	14	5	70	
Current Inspection:	May 16, 2023	14	5	70	
Road AADT:	3,200	Year:	2022		
Inspected By:	José Pineda, Tarek Abdelaziz (Thurber) Arthur Kavulok, Amy Driessen, Kristen Tappenden (TEC)				
Report Attachments:	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items				
Primary Site Issue	Active landslide causing severe deterioration to highway conditions.				
Dimensions:	About 80 m wide (parallel to the highway alignment) and 60 m long (perpendicular to the highway alignment)				
Site History:	<p>In the Spring of 2019 Mr. Gordon Wolters, local MCI of TEC, noticed a sudden severe depression on the highway surface. TEC requested Thurber to conduct a call out.</p> <p>During Thurber's inspection on June 10, 2019, it became clear that the current landslide area is adjacent to a previously repaired landslide in 2007 (previously known as NC06-1).</p> <p>The repairs at the NC06-1 site included the installation of surface and sub-surface drainage improvement measures and the construction of a toe berm to stabilize the landslide movement. The drainage improvement measures consisted of installing sub-drains, constructing a riprap lined swale, flushing, and tying older sub-horizontal drains to a drainage collection manhole at the bottom of the slope. The site NC06-1 was inspected by Thurber as part of the GRMP until 2012 when it was determined that the 2007 remedial measures appeared to have mitigated the slope movement. The instruments installed at the old landslide site are not read under the current GRMP.</p> <p>In 2020, Thurber installed geotechnical instruments, consisting of slope inclinometers and vibrating wire piezometers, within the active landslide area to assess depth of movement and soil and groundwater conditions. These instruments are currently read under the GRMP.</p>				
Maintenance	ACP patch placed in 2021 on the west bound lane covering most of the landslide impacted section of the highway.				
Observations:	Description			Worse?	
<input checked="" type="checkbox"/> Pavement Distress	25 mm dip noted on the middle portion of the 2021 ACP patch.			<input checked="" type="checkbox"/>	

<input checked="" type="checkbox"/> Slope Movement	Reflective wide landslide within the 2021 ACP patch area; diagonal cracks within the landslide area are up to 50 mm wide with up to 25 mm drop across the crack surfaces; multiple tension cracks on the north side slope; guardrail displaced laterally by approximately 300 mm to the north (middle section of the landslide); titling and bent trees in the bush; distinct toe roll near the bush line within the middle section of the landslide	<input checked="" type="checkbox"/>
<input type="checkbox"/> Erosion		<input type="checkbox"/>
<input checked="" type="checkbox"/> Seepage	Water flowing under the 800 mm CSP culvert inlet	<input type="checkbox"/>
<input checked="" type="checkbox"/> Bridge/Culvert Distress	800 mm CSP culvert outlet was damaged; restricted water flow from culvert outlet due to sediment accumulation	<input type="checkbox"/>
<input checked="" type="checkbox"/> Other	Settlement of drill benches, constructed in the winter of 2020 to install geotechnical instruments, created severe open cracks in the highway side slope; the upper settlement crack is about 900 mm from the highway guardrail; water ponding within the highway south ditch	<input type="checkbox"/>
<p>Instrumentation Readings (4 SIs and 7 VWs):</p> <p>SI20-1, installed in the south ditch of the highway, and SI20-4, installed further downslope of the potential toe of the active landslide, continued to show no discernable movement.</p> <p>SI20-2 and SI20-3 installed within the extent of the active landslide have shown movements within the upper 3 m. SI20-2 which is closer to the top of the highway embankment, reinitialized on June 5, 2022, showed a maximum rate of movement of 25.8 mm/yr in the fall of 2022. In the spring of 2023, SI20-2 showed a rate of movement of 14.6 mm/yr, and SI20-3 showed a rate of movement of 0.1 mm/yr.</p> <p>The vibrating wire piezometers showed groundwater depths ranging from 2.12 m in VW20-4A to 7.97 m in VW20-1.</p>		
<p>Observations and Assessment (Refer to attached Figures and Photos):</p> <p>The site condition has deteriorated since the 2022 site inspection visit.</p> <p>The embankment fill at this location was built on a landslide terrain. The deterioration of the highway condition is due to the retrogression of the ancient landslide towards the highway surface. The active movement at this site is relatively shallow based on the SI readings. However, there is still a potential for a future deep-seated movement of the ancient landslide mass. In addition, there is a dormant landslide to the west of the existing culvert, but it is not currently impacting the highway.</p> <p>The landslide is still active as evidenced from the further widening/reopening of reflective cracks on the highway surface. The landslide has three distinct moving blocks, and the middle section is the most active one. Within the middle landslide block, there is a distinct dip on the highway surface, more noticeable on the shoulder, and a significant distress in the highway side slope. The dip on the highway surface creates a rough ride to motorists and the side slope's head scarp will continue to retrogress to take out the guardrail and the highway shoulder.</p> <p>The existing culvert to the west of the active landslide area is in a poor condition.</p> <p>The highway condition is expected to continue deteriorating until an effective remedial measure is implemented. If an accelerated landslide movement occurs at this site, a partial or full road closure may be required.</p>		

Recommendations:

It is recommended that this site be visited again in 2024.

In the short term, the local MCI should monitor the highway periodically for signs of distress and watch closely for the development of new cracks, further opening/widening of existing cracks or drop in highway surface/shoulder (particularly after prolonged rainfall events). Any open surface cracks should be sealed to prevent surface water infiltration into the landslide mass, which would result in further landslide movement and retrogression. Speed reduction signs should also be used, if the highway condition deteriorates significantly, to warn motorists of the existing hazard. Future patching of the highway surface should be done, if needed, to provide a smooth ride to motorists.

Thurber completed a preliminary engineering assessment for this site in 2022. The selected remedial measure by TEC is to install a shallow pile wall to only address the shallow movement at this site. The repair is currently scheduled for implementation in 2024.


Closure

It is a condition of this letter report that Thurber's performance of its professional services will be subject to the attached Statement of Limitations and Conditions.

Tarek Abdelaziz, Ph.D., P.Eng.
Principal | Geotechnical Review Engineer

José Pineda, M.Eng., P.Eng.
Associate | Senior Geotechnical Engineer

H:\32000\32122 AT GRMP Athabasca and Fort McMurray Districts 2021-2025\CAD\2023 GEO HAZARD\JGP\32122 NC006 Drawings.dwg - 1 - Jun. 20, 2023




LEGEND

- APPROXIMATE 2020 INSTRUMENT LOCATION (DEPTH (m))
- APPROXIMATE TEST HOLE (TH) LOCATION
- APPROXIMATE TEST PIT (TP) LOCATION
- APPROXIMATE PNEUMATIC PIEZOMETER (PN) LOCATION
- APPROXIMATE SLOPE INCLINOMETER (SI) LOCATION
- INSTRUMENT NON-OPERATIONAL
- ACTIVE HEADSCARP
- DORMANT SCARP CRACK
- CRACK
- GUARD RAIL
- OVERHEAD POWERLINE
- TREE LINE
- GULLY
- GROUND CONTOUR
- 2021 ACP PATCH
- APPROXIMATE DIRECTION AND NUMBER OF PHOTO

NOTES:

1. SITE FEATURES ARE APPROXIMATE
2. LIDAR PROVIDED BY ALBERTA TRANSPORTATION
3. MAY 16, 2023 OBSERVATIONS SHOWN IN RED




**NORTH CENTRAL
(ATHABASCA AND FORT McMURRAY DISTRICTS)
2023 GEOHAZARD ASSESSMENT**

**NC006: HWY 2:46 MITSUE RECREATION AREA (km 47.6)
SITE PLAN SHOWING LANDSLIDE FEATURES**


FIGURE 1

DRAWN BY	ML
DESIGNED BY	JGP
APPROVED BY	TSA
SCALE	1:1250
DATE	MAY 2023
FILE No.	32122

THURBER ENGINEERING LTD.




SECTION A-A': NC06-1 REPAIRED SITE



SECTION B-B': NC06-2 NEW SITE

- LEGEND**
- 15 I SPT N VALUE
 - ☼ WATER LEVEL IN PIEZOMETER
 - PNEUMATIC PIEZOMETER TIP LOCATION
 - ➔ DEPTH OF MOVEMENT IN SLOPE INCLINOMETER

NOTE
 DATA CONCERNING THE VARIOUS STRATA HAVE BEEN OBTAINED AT THE TEST HOLE LOCATIONS ONLY. THE SOIL STRATIGRAPHY BETWEEN TEST HOLES HAS BEEN INFERRED FROM GEOLOGICAL EVIDENCE AND SO MAY VARY FROM THAT SHOWN.




**NORTH CENTRAL REGION
 (ATHABASCA AND FORT McMURRAY DISTRICTS)
 2023 GEOHAZARD ASSESSMENT**

**NC006: HWY 2:46 MITSUE RECREATION AREA (km 47.6)
 CROSS-SECTIONS**

FIGURE 2

DRAWN BY	ML
DESIGNED BY	JGP
APPROVED BY	TSA
SCALE	1:750
DATE	MAY 2023
FILE No.	32122



THURBER ENGINEERING LTD.



THURBER ENGINEERING LTD.



Photo No. 1 – Looking east toward the landslide and the 2021 ACP patch; more vegetation grew on the highway side slope within the landslide mass



Photo No. 2 – Looking east at reflective cracks near the western limit of the landslide



THURBER ENGINEERING LTD.



Photo No. 3 – Most active landslide block impacting the highway (middle section of landslide mass); note the presence of multiple retrogressive cracks impacting the highway WBL



Photo No. 4 – Looking west at the most active area; note guardrail bowing out by 300 mm



THURBER ENGINEERING LTD.



Photo No. 5 – Middle landslide block: Head scarp crack retrogressing into the highway; 600 to 1.2 m drop from original ground



Photo No. 6 – Looking west at active landslide cracks on the highway side slope; these cracks may reflect the failure of the restored drill benches constructed in the winter of 2020 to install geotechnical instruments.



THURBER ENGINEERING LTD.



Photo No. 7 – 800 mm diameter culvert inlet. Culvert was rusty, partially blocked with vegetation and filled with garbage.



Photo No. 8 – Looking south at patched potholes on the east bound lane



THURBER ENGINEERING LTD.



Photo No. 9 – Looking at 800 mm CSP culvert outlet.