

**ALBERTA TRANSPORTATION AND
ECONOMIC CORRIDORS GRMP
NORTH CENTRAL (ATHABASCA AND FORT
McMURRAY DISTRICTS)
2024 SITE INSPECTION**



Site Number	Location	Name			Hwy	km
NC096	13 Km north of Wandering River	Wandering River Bridge (75731N)			63:04	2.85
Legal Description		UTM Co-ordinates (NAD 83)				
NW 12-73-17 W4		12	N6130357.92	E405776.13		
	Date	PF	CF	Total		
Previous Inspection:	May 17, 2023	15	5	75		
Current Inspection	June 4, 2024	15	5	75		
Road WAADT:	3,920	Year:	2023			
Inspected By:	José Pineda, Tarek Abdelaziz (Thurber) Rocky Wang (TEC)					
Report Attachments:	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input checked="" type="checkbox"/> Maintenance Items					
Primary Site Issue	Two slumps developed beside the NBL bridge south headslope. The west slump exposed NW wing wall and extended below bridge headslope.					
Dimensions:	<p>The slump on the east side of the bridge (Slump 1) is approximately 25 m wide (perpendicular to bridge alignment) and 13 m long (parallel to bridge alignment); the erosion gully to the east of Slump 1 is about 10 m wide, 20 m long, and up to 2.5 m deep.</p> <p>The slump on the west side of the bridge (Slump 2) is approximately 27 m wide (perpendicular to bridge alignment) and 19 m long (parallel to bridge alignment).</p>					
Site History / Available Information:	<p>The existing bridge structure was first in service since 2014 as part of the twining of Highway 63 to Fort McMurray. As part of the bridge construction, the Wandering River was re-aligned by creating a bend that would allow a more perpendicular river flow under the new bridge. The new highway embankment was constructed by placing approximately 4 to 8 m of fill over the native ground on the south and north of the river alignment, respectively. The approach fill head slopes are inclined at 2H:1V and the north head slope also has a 2 m wide bench halfway up the slope. The side slopes of the approach fill are inclined at approximately 3H:1V on both sides of the highway. As part of the bridge construction, the wandering river channel was also realigned to the south.</p> <p>The three-span concrete girder bridge structure has a total length of 51 m. The abutment/wing walls are supported on driven steel H piles (310x125) and the piers are supported on 610 mm diameter x 12.5 mm thick closed end pipe piles filled with concrete.</p> <p>A geotechnical investigation was conducted by EBA in 2011 for the design of the existing bridge. During the 2011 geotechnical investigation, two boreholes were drilled as shown on Figures 1 and 2. Borehole BF3-2, drilled on the north highway embankment, showed that at least 0.6 m of peat were buried under approximately 8 m of fill. Borehole BF3-1, drilled on the south highway embankment, did not</p>					

	<p>encounter any peat. Both boreholes encountered clay till below either the peat or fill. The clay till extended to depths ranging between 15 to 17 m below the ground surface at the time of the investigation. BF3-1 and BF3-2 were terminated in sandstone at elevations of 541 m and 542 m, respectively. Groundwater was measured at an elevation of 561 m and 563 m on the north and south embankments, respectively. The bridge headslope was designed with a factor or safety of 1.3, which is less than typically recommended for bridge headslopes (i.e., a FOS of 1.5).</p> <p>Review of satellite images indicate that the highway NBL east ditch conveys surface drainage from a low-lying area about 135 m to the south of the bridge to the re-aligned river channel; the images also show that a riprap lined channel was constructed at the mouth of the east ditch within the riverbank slope.</p> <p>Slumping of the riverbank by the bridge head slope was first noted by TEC on August 28, 2020.</p> <p>A geotechnical investigation, consisting of drilling four test holes along with the installation of slope inclinometers and piezometers, was completed by Thurber in 2020. The test holes showed the soil conditions mainly consist of medium to high plastic clay fill over high plastic clay over clay till.</p>	
Maintenance /Repairs	Beaver dam that used to block muskeg terrain drainage path located east of the highway southbound lanes was removed and did not reappear since 2022	
Observations:	Description	Worse?
<input checked="" type="checkbox"/> Pavement Distress	25 mm dip within the south approach slab and is more distinct within the western lanes	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Slope Movement	A slump developing on each side of the bridge headslope. Slump 1 on the east side of the highway: head scarp cracks up to 1.5 deep and 1.5 m wide. Slump 2 on the west side of the highway: head scarp cracks up to 4 m deep and 1 m wide; multiple tension cracks within the Slump 2 slide area. The eastern flank of Slump 2 extends under the bridge by at least 2 m, and exposed the underside of the wingwall. Slump 2 sheared off existing 150 mm diameter subdrain pipe and developed a 200 mm gap under the southwest wing wall. Both slumps 1 and 2 are toeing out into the river channel and are narrowing the river channel by approximately 1.2 m; Open, wide cracks noted within the bridge headslope downslope of the abutment seat location and cracks were noted to be wider than last year	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Erosion	Erosion developed east of Slump 1 at the mouth of the north facing riprap lined channel. Erosion became worse in 2023 and it is at least 3.5 m deep and has distorted the existing riprap within the channel. Scattered and subdued riprap areas along the outside bend of the river channel	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> Seepage	Ground surface within Slumps was soft and wet (particularly at Slump 2 location); a steady flow in the highway east ditch originating from the low-lying area located to the south of the bridge location; seepage from	<input type="checkbox"/>

	the outlet of the subdrain pipe located within the east side of the bridge headslope	
<input checked="" type="checkbox"/> Bridge/Culvert Distress	Slump 2 continues to impact the bridge northbound lanes headslope; bridge headslope fill showed signs of distress since 2023	<input checked="" type="checkbox"/>
<input type="checkbox"/> Other	Both slumps restricted the river channel width; sediment accumulation within the stream at the mouth of the erosion gully; more vegetation within Slump 2 mass	<input type="checkbox"/>
<p>Instrumentation Readings (Two SP and Four VW Piezometers; Spring 2024):</p> <p>SI20-1, installed within Slump 1 to the east of the bridge, sheared off at showed at a depth 1.5 m below ground surface. Prior to shearing off, SI20-1 showed a maximum rate of movement of 292 mm/yr. SI20-3, installed within Slump 2 to the west of the bridge, sheared off at 2.1 m below ground surface. Prior to shearing off, SI20-3 showed a maximum rate of movement of 103.1 mm/yr.</p> <p>Standpipe piezometers SP20-2 and SP20-4 showed groundwater depths of 2.5 m and 4.1 m, respectively, corresponding to decreases in groundwater level of 1 m and 0.4 m since the piezometers were last read in Fall 2023.</p> <p>Vibrating wire piezometers VW20-1A, VW20-1B and VW20-3A show current groundwater depths of 2.3 m, 1.7 m, and 0.9 m, respectively. VW20-3B currently shows an above-ground (artesian) groundwater level of -3.3 m. The vibrating wire piezometers showed increases in groundwater level of 0.4 m in VW20-3A and 0.16 m in VW20-3B and decreases in groundwater levels of 1.13 m in VW20-1A and 1.11 in VW20-1B since the instruments were last read in Fall 2023.</p>		
<p>Assessment (Refer to attached Figures and Photos):</p> <p>The site condition deteriorated since the 2023 site inspection.</p> <p>The placement of relatively steeply inclined deep high plastic clay fill (i.e., 2H:1V), elevated groundwater levels within the slope, potential winter construction of embankment fills, and ongoing toe erosion by the river are likely the triggering factors for the observed slumps. In addition, the existing riprap (mainly Class 1M) along the riverbank is relatively smaller in size than what is typically used to armour riverbanks in similar bridge projects.</p> <p>Placement of geogrid layers within the south headslope was recommended in EBA's geotechnical report to achieve the target factor of safety. It is suspected that the geogrid layers were not placed within the bridge headslope or approach fills, and this may have been another contributing factor to observed instabilities. However, there are no detailed construction notes/records to confirm this hypothesis.</p> <p>The existing erosion gully has become wider and deeper than observed in 2023. It appears that the east ditch was not properly designed to carry the current flow. It is anticipated that the gully will continue get deeper and wider with time, resulting in more sediment accumulation in the stream and loss of land/trees to the east of the gully.</p> <p>The slumps within the south approach fills, on each side of the bridge, did not appear to have yet impacted the integrity of the bridge and the highway. However, Slump 2 has exposed the base of the NW wing wall and its flank extended below the headslope of the bridge downslope of the abutment location. Slump 2 is considered more critical than Slump 1 in terms of its potential impact on the highway and the bridge conditions.</p> <p>The approach fill slumps, to the east and the west of the bridge headslope, are very active, moving at very high rates and will continue to grow bigger in size. Future erosion of the toe of the landslides at the river location and/or rise in groundwater levels within the landslides may result in (a) failure of the majority of the headslope under the bridge deck, and (b) distress of the wing walls and exposure of abutment seat and a few of the pile supports (particularly at Slump 2 location). In addition, the complete failure of these closely spaced slumps, if occurs with time, could significantly restrict the width of the river channel and (a) cause flooding of areas located upstream of the site and/or (b) result in the</p>		

development of additional slumps above the restricted channel width on the north side of the bridge.

The bridge headslope, between the two slumps, is likely in a meta-stable condition and the complete failure of the headslope may take place abruptly similar to the currently active slumps. The observed cracks within the headslope may reflect a slope movement. The dip noted on the highway approach slab could be a reflection of the headslope movement.

A structural assessment completed in 2022 indicated that the bridge structure may not be impacted in response to future movements of the slopes. However, the roadway condition will be significantly impacted. If the roadway fails at this location in response to future landslide movements, a major detour will be required. Alternatively, the SBLs may be used to accommodate traffic through this area.

Recommendations:

This site should be visited again in the spring of 2025.

Short-Term Repair Measures

In the short term, consideration should be given for the following:

- Monitor the highway periodically for signs of distress and watch closely for the development of new cracks or widening of existing cracks.
- Monitor existing cracks under the bridge headslope and check for signs of movement of the headslope.
- Place heavy rock riprap (Min. Class 1) at the base of the slumps (near the river location) to provide additional buttress and erosion protection.
- Reshape the failed riprap-lined channel within the east ditch and add heavy rock riprap (Min Class 2) to armor the re-graded channel. This should prevent future accumulation of sediment in the river channel and reduce the probably of further loss of land/trees to the east of the gully location.
- Undertake slight grading to seal open cracks within landslide masses.
- Insert a flexible HDPE pipe into the void below the NW wing wall to convey as much flow as possible from the location of the sheared off subdrain pipe to the river channel.

Long-Term Repair Measures

Various long-term repair options were presented in the preliminary engineering report prepared by Thurber in 2022 to deal with the ongoing stabilities of the active slumps and potential future instability of the meta-stable bridge headslope. The repair options included: a) dig and replace with granular material, b) installation of soil nails, c) installation of sheet pile walls, or d) a combination of options a) to c). In 2023, TEC selected the dig and replace option for Slumps 1 and 2 along with the implementation of erosion protection measures within the east ditch and along the south bank of the river at the bridge location. The detailed design is currently underway.

Closure:

It is a condition of this letter report that Thurber's performance of its professional services will be subject to the attached Statement of Limitations and Conditions.

Tarek Abdelaziz, Ph.D., P.Eng.
Partner | Senior Geotechnical Engineer

José Pineda, M.Eng., P.Eng.
Associate | Senior Geotechnical Engineer



STATEMENT OF LIMITATIONS AND CONDITIONS

1. STANDARD OF CARE

This Report has been prepared in accordance with generally accepted engineering or environmental consulting practices in the applicable jurisdiction. No other warranty, expressed or implied, is intended or made.

2. COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment are a part of the Report, which is of a summary nature and is not intended to stand alone without reference to the instructions given to Thurber by the Client, communications between Thurber and the Client, and any other reports, proposals or documents prepared by Thurber for the Client relative to the specific site described herein, all of which together constitute the Report.

IN ORDER TO PROPERLY UNDERSTAND THE SUGGESTIONS, RECOMMENDATIONS AND OPINIONS EXPRESSED HEREIN, REFERENCE MUST BE MADE TO THE WHOLE OF THE REPORT. THURBER IS NOT RESPONSIBLE FOR USE BY ANY PARTY OF PORTIONS OF THE REPORT WITHOUT REFERENCE TO THE WHOLE REPORT.

3. BASIS OF REPORT

The Report has been prepared for the specific site, development, design objectives and purposes that were described to Thurber by the Client. The applicability and reliability of any of the findings, recommendations, suggestions, or opinions expressed in the Report, subject to the limitations provided herein, are only valid to the extent that the Report expressly addresses proposed development, design objectives and purposes, and then only to the extent that there has been no material alteration to or variation from any of the said descriptions provided to Thurber, unless Thurber is specifically requested by the Client to review and revise the Report in light of such alteration or variation.

4. USE OF THE REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. NO OTHER PARTY MAY USE OR RELY UPON THE REPORT OR ANY PORTION THEREOF WITHOUT THURBER'S WRITTEN CONSENT AND SUCH USE SHALL BE ON SUCH TERMS AND CONDITIONS AS THURBER MAY EXPRESSLY APPROVE. Ownership in and copyright for the contents of the Report belong to Thurber. Any use which a third party makes of the Report, is the sole responsibility of such third party. Thurber accepts no responsibility whatsoever for damages suffered by any third party resulting from use of the Report without Thurber's express written permission.

5. INTERPRETATION OF THE REPORT


- a) Nature and Exactness of Soil and Contaminant Description: Classification and identification of soils, rocks, geological units, contaminant materials and quantities have been based on investigations performed in accordance with the standards set out in Paragraph 1. Classification and identification of these factors are judgmental in nature. Comprehensive sampling and testing programs implemented with the appropriate equipment by experienced personnel may fail to locate some conditions. All investigations utilizing the standards of Paragraph 1 will involve an inherent risk that some conditions will not be detected and all documents or records summarizing such investigations will be based on assumptions of what exists between the actual points sampled. Actual conditions may vary significantly between the points investigated and the Client and all other persons making use of such documents or records with our express written consent should be aware of this risk and the Report is delivered subject to the express condition that such risk is accepted by the Client and such other persons. Some conditions are subject to change over time and those making use of the Report should be aware of this possibility and understand that the Report only presents the conditions at the sampled points at the time of sampling. If special concerns exist, or the Client has special considerations or requirements, the Client should disclose them so that additional or special investigations may be undertaken which would not otherwise be within the scope of investigations made for the purposes of the Report.
- b) Reliance on Provided Information: The evaluation and conclusions contained in the Report have been prepared on the basis of conditions in evidence at the time of site inspections and on the basis of information provided to Thurber. Thurber has relied in good faith upon representations, information and instructions provided by the Client and others concerning the site. Accordingly, Thurber does not accept responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of misstatements, omissions, misrepresentations, or fraudulent acts of the Client or other persons providing information relied on by Thurber. Thurber is entitled to rely on such representations, information and instructions and is not required to carry out investigations to determine the truth or accuracy of such representations, information and instructions.
- c) Design Services: The Report may form part of design and construction documents for information purposes even though it may have been issued prior to final design being completed. Thurber should be retained to review final design, project plans and related documents prior to construction to confirm that they are consistent with the intent of the Report. Any differences that may exist between the Report's recommendations and the final design detailed in the contract documents should be reported to Thurber immediately so that Thurber can address potential conflicts.
- d) Construction Services: During construction Thurber should be retained to provide field reviews. Field reviews consist of performing sufficient and timely observations of encountered conditions in order to confirm and document that the site conditions do not materially differ from those interpreted conditions considered in the preparation of the report. Adequate field reviews are necessary for Thurber to provide letters of assurance, in accordance with the requirements of many regulatory authorities.


6. RELEASE OF POLLUTANTS OR HAZARDOUS SUBSTANCES

Geotechnical engineering and environmental consulting projects often have the potential to encounter pollutants or hazardous substances and the potential to cause the escape, release or dispersal of those substances. Thurber shall have no liability to the Client under any circumstances, for the escape, release or dispersal of pollutants or hazardous substances, unless such pollutants or hazardous substances have been specifically and accurately identified to Thurber by the Client prior to the commencement of Thurber's professional services.

7. INDEPENDENT JUDGEMENTS OF CLIENT


The information, interpretations and conclusions in the Report are based on Thurber's interpretation of conditions revealed through limited investigation conducted within a defined scope of services. Thurber does not accept responsibility for independent conclusions, interpretations, interpolations and/or decisions of the Client, or others who may come into possession of the Report, or any part thereof, which may be based on information contained in the Report. This restriction of liability includes but is not limited to decisions made to develop, purchase or sell land.





NOTES:

1. JUNE 4, 2024 OBSERVATIONS ARE SHOWN IN RED.
2. SLUMP 1 IS WITHIN THE RIVERBANK SLOPE TO THE EAST OF THE BRIDGE HEADSLOPE.




**NORTH CENTRAL REGION
(ATHABASCA AND FORT McMURRAY DISTRICTS)
2024 GEOHAZARD ASSESSMENT**

**CROSS - SECTION A - A'
SHOWING SLUMP 1 - EAST OF BRIDGE HEADSLOPE**

FIGURE 2

DRAWN BY	ML
DESIGNED BY	JGP
APPROVED BY	TSA
SCALE	1:250
DATE	JULY 2024
FILE No.	32122



THURBER ENGINEERING LTD.



Photo No. 1 – Looking northeast at the low-lying area south of the Bridge



Photo No. 2 – Looking north at north facing riprap channel to the east of the bridge location. Note the deep erosion along the channel.



Photo No. 3 – Looking southeast at the same area in Photo No. 2



Photo No. 4 – Slumping within the riverbanks to the east of the Hwy (slump 1) and to the west of the Hwy (slump 2). Note distinct toe rolls in the river channel.



Photo No. 5 – Looking southwest at Slump No. 2. Vegetation has grown within the slump since the 2023 inspection.



Photo No. 6 – Looking at Crack on head slope extending to the subdrain on the east side of the bridge. Crack is 5 mm wide at the subdrain and 700 mm wide at 10 m west of the subdrain.



Photo No. 7 – Looking southeast at Slump No. 2 flank. Note: (a) eastern flank of slump extending below the bridge headslope and (b) extensive cracking and presence of a distinct longitudinal crack below bridge headslope



Photo No. 8 – Dip at the bridge south approach slab appears to have dropped more; and it is more noticeable within the western half between the yellow line and the edge of pavement above Slump 2