

**ALBERTA TRANSPORTATION  
GEOHAZARD ASSESSMENT PROGRAM  
NORTH CENTRAL REGION – ATHABASCA  
2020 INSPECTION**



**THURBER ENGINEERING LTD.**

Site Number	Location	Name	Hwy	km
NC088	62 Km N of Wandering River	<b>Km 108 Settlement</b>	63:06	6.0
Legal Description		UTM Co-ordinates (NAD 83)		
S-30-77-14-W4M		12	6172629	E 426672

	Date	PF	CF	Total
<b>Previous Inspection:</b>	May 8, 2018	13	6	78 (Highway 63 NBL)
	May 8, 2018	14	5	70 (Highway 63 SBL)
<b>Current Inspection:</b>	June 24, 2020	9	5	45 (Highway 63 NBL)
		7	4	28 (Highway 63 SBL)
<b>Road AADT:</b>	4,020	<b>Year:</b>	2019	
<b>Inspected By:</b>	Tarek Abdelaziz and José Pineda (Thurber) Arthur Kavulok and Roger Skirrow (TRANS)			
<b>Report Attachments:</b>	<input checked="" type="checkbox"/> Photographs <input checked="" type="checkbox"/> Plans <input type="checkbox"/> Maintenance Items			
<b>Primary Site Issue</b>	<p><b>NBL:</b> A landslide above the original pipe causing a severe pavement distress on the highway north bound lanes and east embankment slope; localized slump above the inlet of the culvert</p> <p><b>SBL:</b> A localized slump in the west embankment around and above the outlet of the smooth wall steel pipe installed in 2018, resulted in the formation of multiple tension cracks within the entire embankment and failure of a 12 m section of the pipe at the outlet location.</p>			
<b>Dimensions:</b>	<p><b>NBL:</b> The pavement distress section is about 25 to 30 m long. The landslide is about 30 m wide parallel to the highway and 40 m long perpendicular to the highway alignment.</p> <p><b>SBL:</b> Local sinkhole at the toe of the embankment was approximately 5 m wide, 15 m long, and 3 to 4 m deep; cracking near the top of the embankment used to be 150 m long.</p>			
<b>Site History:</b>	<p>The NBL embankment was constructed during the Hwy 63 twinning project. Up to 14 m of fill was placed to construct the NBL at the subject location to cross the valley of an existing creek. A 1,200 mm CSP pipe was connected to an existing 1,200 mm concrete pipe to convey the creek flow below the new embankment. It is understood that the highway was built in 2014 and paved in October 2016.</p> <p>In the fall of 2017, the CSP pipe collapsed at about 30 m from the inlet location (as per the information provided by AT). Slumping and erosion were also noted at the outlet of the concrete pipe (west side of SBL embankment). Recommendations were provided in the fall 2017 callout report to install a new pipe and to grout the old pipe. The proposed alignment of the new pipe was provided in the callout report. The recommended alignment of the replacement pipe was selected to avoid areas of potential instability on the east and west sides of the highway. ACP patch was placed in 2017 and the guardrail was severely distorted and had to be replaced in 2017.</p> <p>In the winter of 2018, a new 170 m long 1.2 m dia. SWSP culvert was installed through the embankment using the pilot tube micro-tunneling technology. The new pipe was installed immediately to the north of the existing culvert (installed from the outlet location on the</p>			

	<p>west side towards the inlet location on the east side), and the old culvert was grouted and abandoned. As per the information provided by AT, the construction involved excavating a pit at the toe of the west embankment, where an old localized slump existed. During the May 2018 site inspection, a large cavity was noted at the toe of the west embankment and the flow bypassed the new pipe to wash out the old slump. A CCTV inspection conducted on the new pipe indicated a rupture at 12 m from the outlet location.</p> <p>Additional repairs were conducted between December 2018 and June 2019 consisting of (a) benched excavation of east and west slopes to replace damaged pipe section at culvert outlet location and repair localized slump around culvert inlet location, (b) backfilling excavations using compacted granular fill, (c) grading median ditch to promote surface drainage, (d) placement of Type C blanket, riprap and rock check dams for erosion protection, and (e) topsoil and seeding of all disturbed areas. A 62 m long ACP patch was placed on the NBLs in June 2020. The NBLs guardrail was also replaced in June 2020.</p>	
<b>Observations:</b>	<b>Description</b>	<b>Worse?</b>
<input checked="" type="checkbox"/> Pavement Distress	<b>NBL:</b> No visible dip noted on the highway after recent ACP patch <b>SBL:</b> N/A	<input type="checkbox"/>
<input checked="" type="checkbox"/> Slope Movement	<b>SBL:</b> 13 m long x 70 mm wide x 100 mm deep crack on the west side slope, approximately 1.5 m from the guardrail <b>NBL:</b> Minor slope dishing on the side slope	<input type="checkbox"/>
<input checked="" type="checkbox"/> Erosion	<b>NBL:</b> Local erosion along the south facing riprap channel (north of the SWSP culvert inlet) <b>SBL:</b> Water ponding to the west of the SWSP culvert outlet location before it flows into the creek channel, resulting in slight bank erosion to the west of SWSP culvert outlet	<input type="checkbox"/>
<input type="checkbox"/> Seepage		<input type="checkbox"/>
<input type="checkbox"/> Bridge/Culvert Distress		<input type="checkbox"/>
<input checked="" type="checkbox"/> Other	Vegetated slopes with the exception of a small area above the SWSP culvert inlet location; water is still ponding in the median ditch before it flows into the CSP culvert; water is flowing into the 1.2 m diameter SWSP culvert and in the 800 mm CSP median culvert	<input type="checkbox"/>
<b>Instrumentation (2SI and 4 PNs):</b>		
<p>Slope inclinometer SI18-3, installed on the east highway embankment, showed a rate of movement of 6.3 mm/yr over 6.5 m to 11.3 m depth since Spring 2019, corresponding to a decrease in the rate of movement of 47.7 mm/yr over the same period. Movement plots for SI18-3 suggest that the embankment fill is settling and affecting the shape of the SI casing. SI18-4, installed in the west highway embankment, showed no discernible movement.</p> <p>The groundwater levels ranged between 3.7 m to 8.2 m below ground surface. Since Spring 2019, the groundwater levels decreased in the pneumatic piezometers by up to 1.6 m.</p>		
<b>Assessment (Refer to attached Figures and Photos):</b>		
<p>The repairs completed between 2018 and 2019 appear to have performed well to date.</p> <p>There is still a concern regarding the stability of the east embankment. It is suspected that ongoing</p>		

movement will take place, resulting in re-appearance of a dip in the highway surface. Water ponding in the median ditch will continue to elevate groundwater levels in the east slope and this may result in future accelerated movement of the landslide.

There are no visible signs of instability in the west slope except for the observed crack near the top of the slope. However, it is suspected that this crack may have been created by the mowing equipment. This will need to be confirmed during future site inspections.

Permanent erosion control measures installed during the 2018-2019 repairs have some deficiencies that need to be addressed to prevent further erosion and future slumping issues. The erosion control measures deficiencies include bare vegetation zone above the SWSP culvert inlet, and localized erosion gullies along the south facing riprap channel of the east slope.

#### **Recommendations:**

The site should also be inspected again in the Spring of 2021 to confirm the effectiveness of the remedial measures.

#### **Short Term Measures**

The MCI should periodically monitor the highway lanes and the slopes for signs of movement. If the dip re-appears on the highway NBLs, additional ACP patch should be placed to eliminate the dip and provide a smooth ride to motorists.

The median ditch should be slightly graded to prevent ponding of water in the ditch.

It is recommended to get the creek channel slightly realigned at the SWSP culvert outlet to prevent ponding of water at the toe of the slope. Additional riprap armoring of the creek channel (for at least 5 to 10 m beyond the outlet location) is also recommended to reduce the likelihood of future toe erosion issues.

Erosion gullies within the south facing channel of the east slope will need to be repaired. This will require salvaging existing riprap, excavating eroded areas, reshaping the channel to have well defined sides and bottom, placement of salvaged riprap and additional riprap (as needed) over non-woven geotextile fabric (to be keyed in at least 300 mm at the top of the channel) along the sides and the bottom of the channel.

#### **Long Term Measures:**

If the east slope continues to move in the future, the following provides potential long-term remedial options:

Option 1: Construct a toe berm to buttress the landslide. This option will require in-stream work to divert the creek flow, land acquisition, extending existing pipe, tree clearing, and the reconstruction of the riprap lined channels. Regularity authority approvals will be required to complete this option. The ballpark cost of this option is in the range of \$600,000 to \$700,000, excluding engineering.



Option 2: Excavate and replace the landslide mass with gravel or geogrid reinforced clay. This option will require temporary closure of the highway and the construction of a detour. The ballpark cost of this option is in the range of \$1,000,000 (geogrid reinforced clay) to \$1,600,000 (gravel), excluding engineering.

Option 3: Offload the top of the slope and backfill excavated mass using light weight fill (i.e. cellular concrete or EPS blocks). This option may require partial closure of the highway (i.e. alternating lane traffic). The ballpark cost of this option is in the range of \$700,000 to \$900,000 (excluding engineering), depending on the depth of replacement.

Option 4: Construct a 35 to 40 m long tied-back tangent pile wall along the east side of the highway along with slope flattening above the culvert location. This option does not require closure of the highway. The ballpark cost of this option is in the range of \$1,000,000 to 1,400,000 (excluding engineering).



H:\13000\13357 Geohazard Assessment - Athabasca (CON0017605)\Drafting\2020\JGP\13357 NC088 FIGURE 1.dwg - 11N - Oct. 09, 2020




**LEGEND**

- APPROXIMATE THURBER TEST HOLE LOCATION
- SI SLOPE INCLINOMETER
- PN PNEUMATIC PIEZOMETER
- SP STANDPIPE PIEZOMETER
- APPROXIMATE AMEC TEST HOLE LOCATION
- PAVED OVER INSTRUMENT
- CULVERT NUMBER AND DIAMETER (AS OF 2017)
- HIGHWAY CENTER LINE
- GUARD RAIL
- OLD CRACK / SCARP
- EXTENT OF DIP IN MAY 2018
- CREEK
- PHOTOGRAPH NUMBER, AND APPROXIMATE DIRECTION AND LOCATION

**NOTES:**

1. LIDAR FLOWN BEFORE NORTHBOUND LANE WAS CONSTRUCTED. CONTOURS ARE BASED ON 2007 LIDAR DATA.
2. FEATURE LOCATIONS ARE APPROXIMATE.
3. PREVIOUS OBSERVATIONS SHOWN IN BLACK.
4. JUNE 24, 2020 FEATURES SHOWN IN RED.



**2020 GEOHAZARD ASSESSMENT  
NORTH CENTRAL REGION (ATHABASCA AREA)**

**NC088: HWY 63:06 NBL (km 4.9) PAVEMENT DISTRESS  
SKETCH SHOWING SITE FEATURES**

**FIGURE 1**

DRAWN BY	ML
DESIGNED BY	JGP
APPROVED BY	TSA
SCALE	1:1000
DATE	AUGUST 2020
FILE No.	13357

**THURBER ENGINEERING LTD.**





Photo No. 1 – Looking north at ACP patch recently placed along the north bound lanes (NBLs)



Photo No. 2 – Looking south at NBL embankment side slope; note minor rills near the guardrail





Photo No. 3 – NBL Embankment side slope; note vegetation growth and erosion of the creek bank at the toe of the slope



Photo No. 4 - New rock check dam located in the northeast ditch of the highway





Photo No. 5 – CSP culvert C3 outlet



Photo No. 6 – Looking southeast toward the 1.2 m SWSP inlet; note erosion along the south facing riprap channel and deadfall accumulation near the inlet





Photo No. 7 – Riprap channel erosion and debris accumulation near the 1.2 m SWSP culvert inlet



Photo No. 8 – Looking inside the SWSP culvert from inlet location





Photo No. 9 – NBL embankment east side slope; note poor vegetation growth upslope of the centre portion of the riprap



Photo No. 10 – Rock check dams located along NBL southeast ditch





Photo No. 11 – Median ponding water; note recently placed ACP patch on the NBL



Photo No. 12 – Looking south at SBL west side slope; note good vegetation growth within recently repaired area





Photo No. 13 – New north facing riprap channel along the SBL west side slope



Photo No. 14 – New SWSP outlet; note water flow and minor erosion downstream of the outlet