# STONY PLAIN REGION GEOHAZARD RISK ASSESSMENT SITE INSPECTION FORM

SITE NUMBER AND NAME:	HIGHWAY AND KM:	PREVIOUS INSPECTION DATE:	INSPECTION DATE:		
NC 22 - Pavement Dip	Hwy 759:02, km 1.42	May 20, 2010	June 14, 2011		
LEGAL DESCRIPTION:	NAD 83 COORDINATES:	RISK ASSESSMENT:			
NW 11-49-6-W5M	-51362 E, 5898567 N	PF: 9 CF: 2 <b>TOTAL:</b>	TAL: 18		

SUMMARY OF SITE INSTRUMENTATION:	INSPECTED BY:
	Adam Gmeinweser, P. Eng. (EBA)
Survey pins	Chris Gräpel, P. Eng. (EBA)
	Sabhago Oad, P. Eng. (TRANS)
	Fred Cheng, P. Eng. (TRANS)
	Trea Cheng, T. Eng. (Treativo)
LAST READING DATE:	
DDIMADY SITE ISSUE: Section of exploit with as much as 0.6 m actiloment	
PRIMARY SITE ISSUE: Section of asphalt with as much as 0.6 m settlement	
APPROXIMATE DIMENSIONS: 30 m in length	
DATE OF DEMENDIAL ACTION	
DATE OF REMEDIAL ACTION:	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		30 m long strip of asphalt; 0.6 m maximum settlement		X
Slope Movement		X			
Erosion		X			
Seepage		X			
Culvert Distress	X		Culvert south of pavement dip; blocked with static water		X

## **COMMENTS:**

Location and site plan shown on Figure NC-22.

Site conditions shown in Photos 1 and 2.

Risk level unchanged from 2010.

Foam columns installed in Spring 2010 – performing well so far.

Asphalt pavement placed after foam injection in Spring 2010.

Survey pins installed in new asphalt to monitor settlement.

## STONY PLAIN REGION GEOHAZARD RISK ASSESSMENT SITE INSPECTION FORM

## **SITE OBSERVATIONS:**

- Length of pavement dip area is approximately 30 m long and appears to be relatively uniform across the width of the pavement;
- Pavement dip appeared to be about 0.6 m before foam injection implemented;
- Embankment is about 3 m high with approximately 3H:1V sideslopes outside of the dip;
- Sideslopes within dip area are concave and steep (about 1H:1V);
- New asphalt pavement placed in summer 2010. Cracks beginning to reflect through new pavement;
- 800 mm diameter culvert located south of the pavement dip. Culvert appears to be blocked and standing water is located within the ditch on both sides of the highway;
- Small sinkhole observed about 3 m east of the west outlet of the culvert. Relatively unchanged from 2008 inspection;
- Deflection of barbed wire fence observed at toe of east embankment (i.e. northbound lane); and
- Lateral spreading of embankment suspected due to concave shape of sideslopes in dip area and deflection of the barbed wire fence.

### **RECOMMENDATIONS:**


- Continue to monitor survey pins installed as part of the foam injection study.
- MCI should replace the existing culvert and develop a construction plan for improvement of both ditches.
- TRANS operations staff and EBA to discuss milling pavement versus levelling asphalt with pavement options.



Photo 1: Asphalt overlay placed after foam injection



Photo 2: Repaired pavement dip facing northeast



4. REFERENCE POINT - RELATIVE ELEVATION 100.0 m

**CONCAVE SIDE SLOPES** 

OFFICE

EDM

A TETRATECH COMP

November 18, 2011



Photo 1: Asphalt overlay placed after foam injection



Photo 2: Repaired pavement dip facing northeast