



**SOUTHERN REGION GEOHAZARD ASSESSMENT  
ANNUAL ASSESSMENT REPORT  
2007**

Submitted to:

**Alberta Infrastructure and Transportation**  
Calgary, Alberta

Submitted by:

**AMEC Earth & Environmental,**  
**a division of AMEC Americas Limited**  
Calgary, Alberta

November 2007

CG25263



November 6, 2007  
CG25263

Mr. Roger Skirrow, M.Sc., P.Eng.  
Alberta Infrastructure and Transportation  
2<sup>nd</sup> Floor, Twin Atria Building  
4999 – 98 Avenue  
Edmonton, AB T6B 2X3

Dear Roger:

**Re: Southern Region Geohazard Assessment  
Annual Assessment Report, 2007**

Please find enclosed one copy of the 2007 Annual Assessment Report. Also included is an unbound copy of the appendices for inclusion in the appropriate site binders and a CD containing electronic copies of the report files. Copies of these items have also been sent to Ross Dickson of Alberta Infrastructure and Transportation in Calgary.

If you have any questions or require any further information, please do not hesitate to contact the undersigned at (403) 569-6529.

Yours truly,  
**AMEC Earth & Environmental,  
a division of AMEC Americas Limited**

Andrew Bidwell, M.Eng., P.Eng.  
Associate Geological Engineer

AB

c: Ross Dickson – AIT

AMEC Earth & Environmental  
a division of AMEC Americas Limited  
221 – 18<sup>th</sup> Street S.E.  
Calgary, Alberta  
CANADA T2E 6J5  
Tel + 1 (403) 248-4331  
Fax + 1 (403) 248-2188  
www.amec.com

R:\Projects\Calgary Geo\CG25263 - AIT Southern Region 2007\600 Reports\2007 Annual Inspections\AIT S Region 2007 Annual Assessments .doc



## TABLE OF CONTENTS

	PAGE
<b>1.0 INTRODUCTION.....</b>	<b>3</b>
<b>2.0 BACKGROUND.....</b>	<b>3</b>
<b>3.0 FIELD PROGRAM.....</b>	<b>3</b>
<b>4.0 ANNUAL ASSESSMENT RESULTS.....</b>	<b>5</b>
4.1 S1 – JUMPINGPOUND CREEK.....	5
4.2 S2 – PRIDDIS.....	10
4.3 S3 – COCHRANE.....	15
4.4 S4 – WILLOW CREEK.....	18
4.5 S5 – CHIN COULEE.....	22
4.6 S7 – MILLARVILLE.....	27
4.7 S8 – FISHER CREEK.....	30
4.8 S10 – HIGHWAY 762 S10(A).....	34
4.9 S10 – HIGHWAY 762 S10(C).....	37
4.10 S12 – SPRAY LAKES ROAD.....	41
4.11 S14 – BELLEVUE SITES.....	44
4.11.1 Potential Sinkhole Area.....	44
4.11.2 Rock Cut.....	46
4.12 S15 – CROWSNEST LAKE ROCKFALL BARRIER.....	49
4.13 S16 – CHAIN LAKES SITE.....	54
4.14 S17 – HIGHWAY 40 – MOUNT BALDY ROCK CUT.....	59
4.15 S18 – HIGHWAY 40 – GALATEA CREEK THROUGH-CUT.....	62
4.16 S19 – HIGHWAY 40 – KING CREEK.....	68
4.17 S20 – HIGHWAY 541 – HIGHWOOD HOUSE ROCK CUT.....	72
4.18 S21 – HIGHWAY 541 – HIGHWOOD BASE ROAD CREEK.....	76
4.19 S22 – HIGHWAY 762 “S CURVE” SITE.....	79
4.20 S23 – HIGHWAY 507:02 – EAST OF MILL CREEK.....	82
4.21 S24 – HIGHWAY 507 – EASTBOUND AND WESTBOUND LANE SITES.....	89
4.21.1 Eastbound Lane Site.....	89
4.21.2 Westbound Lane Site.....	91
4.22 S25 – HIGHWAY 3 – MONARCH.....	96



4.23	S26 – HIGHWAY 41 – ELKWATER .....	99
4.24	S27 – HIGHWAY 3 – WINDMILL .....	102
4.25	S28 – HIGHWAY 3A AT RANGE ROAD 2-2A .....	104
4.26	S29 – HIGHWAY 1 – SEVEN PERSONS CREEK .....	108
<b>5.0</b>	<b>SUMMARY .....</b>	<b>110</b>
<b>6.0</b>	<b>CLOSURE .....</b>	<b>110</b>

### LIST OF APPENDICES

Appendix A – Tables
Appendix S1 – Jumpingpound Creek
Appendix S2 – Priddis
Appendix S3 – Cochrane
Appendix S4 – Willow Creek
Appendix S5 – Chin Coulee
Appendix S7 – Millarville
Appendix S8 – Fisher Creek
Appendix S10(A) – Highway 762 S10(A)
Appendix S10(C) – Highway 762 S10(C)
Appendix S12 – Spray Lakes Road
Appendix S14 – Bellevue Sites
Appendix S15 – Crowsnest Lake Rockfall Barrier
Appendix S16 – Chain Lakes Site
Appendix S17 – Highway 40 – Mount Baldy Rock Cut
Appendix S18 – Highway 40 – Galatea Creek Through-Cut
Appendix S19 – Highway 40 – King Creek
Appendix S20 – Highway 541 – Highwood House Rock Cut
Appendix S21 – Highway 541 – Highwood Base Road Creek
Appendix S22 – Highway 762 “S” Curve Site
Appendix S23 – Highway 507:02 – East Of Mill Creek
Appendix S24 – Highway 507 – Eastbound And Westbound Lane Sites
Appendix S25 – Highway 3 – Monarch
Appendix S26 – Highway 41 - Elkwater
Appendix S27 – Highway 3 - Windmill
Appendix S28 – Highway 3A At Range Road 2-2A
Appendix S29 – Highway 1 – Seven Persons Creek

## 1.0 INTRODUCTION

AMEC Earth & Environmental (AMEC), a division of AMEC Americas Limited (AMEC), has been retained by Alberta Infrastructure and Transportation (AIT) to conduct annual assessments of identified geohazard sites in the Southern Region. This work is being done in conjunction with semi-annual instrumentation monitoring at several of the identified geohazard sites.

This report presents the results of the 2007 annual assessments along with recommendations for continued assessment, monitoring and additional work where required. The enclosed CD contains electronic copies of the report files.

This work has been authorized by AIT under Consulting Services Agreement CE044/2004.

## 2.0 BACKGROUND

AIT has implemented a Geotechnical Risk Management Plan (GRMP) in order to estimate the risk levels of geohazard events at specific sites and to assist AIT in the prioritization of mitigative works. This work has been conducted in the past by AIT personnel and since 2000 by outside geotechnical consultants with the work being awarded on a regional basis. AMEC has been awarded the assignment of conducting this work for the Southern Region since the spring of 2000.

The GRMP includes the estimation of a Risk Level for each site that is assessed. The estimated Risk Level is expressed as a number ranging from 1 to 200 that is calculated as the product of a Probability Factor and a Consequence Factor assigned to each site on the basis of annual site assessments, geotechnical instrumentation readings, and other information for each specific site. The descriptions for these factors are listed on Tables A1 to A3 in Appendix A. Table A1 lists general descriptions for these factors, as provided by AIT. Tables A2 and A3 list the sets of probability and consequence factors specific to rockfall hazards and debris flows, respectively, as developed by AMEC for AIT during a recent geohazards review of the Highway 40/Highway 541 corridor.

## 3.0 FIELD PROGRAM

The annual assessments were performed on June 18 to 21, 2007 for the following sites.

### June 18, 2007

- S2 – Priddis
- S7 – Millarville
- S10 – Highway 762 S10(C)
- S8 – Fisher Creek
- S22 – Highway 762 “S” Curve
- S10 – Highway 762 S10(A)
- S1 – Jumpingpound Creek
- S3 – Cochrane

June 19, 2007

S12 – Spray Lakes Road  
S17 – Highway 40 – Mount Baldy Rock Cut  
S18 – Highway 40 – Galatea Creek Through-Cut  
S19 – Highway 40 – King Creek  
S20 – Highway 541 – Highwood House Rock Cut  
S21 – Highway 541 – Highwood Base Road Creek  
S16 – Chain Lakes Site

June 20, 2007

S15 – Crowsnest Lake Rockfall Barrier  
S14 – Bellevue Sites  
S27 – Highway 3 – Windmill  
S28 – Highway 3A At Range Road 2-2A  
S23 – Highway 507:02 – East Of Mill Creek  
S24 – Highway 507 – Eastbound Lane Site and Westbound Lane Site  
S4 – Willow Creek  
S25 – Highway 3 – Monarch

June 21, 2007

S5 – Chin Coulee  
S26 – Highway 41 – Elkwater  
S29 – Highway 1 – Seven Persons Creek

Each site was visited by Andrew Bidwell of AMEC along with Roger Skirrow and Rocky Wang of AIT. Ross Dickson of AIT participated in the site visits on June 19 to 21, 2007.

Each site was assessed visually and measurements and notes of site features were recorded using field reconnaissance level techniques. Digital photographs of site features were also taken.

#### **4.24 S27 – HIGHWAY 3 – WINDMILL**

##### **Site Description and Background**

This site is located on Highway 3, a short distance westbound from the junction between Highway 3 and Highway 22 and approximately 1 km eastbound from a large wind turbine on the south side of the road. Please refer to Figure S27-1 in Appendix S27 for an illustration of the site location.

The highway is oriented northeast/southwest at this site, with a single eastbound lane and two westbound lanes (primary lane and a climbing lane). The natural ground surface around the site slopes down gently towards the Crowsnest River channel which is roughly 300 m to the south of the highway. The highway is constructed on a small fill embankment with the south embankment fill slope at approximately 15° inclination and roughly 4 to 5 m high.

The June 2007 site inspection by AMEC and AIT personnel was the first annual inspection as part of the Southern Region GRMP. This site was added to the inspection list because AIT personnel had noted road surface cracking and a possible settlement issue at this site. AMEC understands that there is anecdotal reporting by AIT personnel of a crack and settlement at this site back from as far back as the 1980's.

##### **Site Assessment**

The site assessment was performed on June 20, 2007. The weather at the time of the site assessment was clear and warm.

The site assessment consisted of a visual review of the highway surface at the site as well as a traverse of the slope below (south of) the highway.

##### **Observations**

The following points summarize the observations made during the site assessment. Please also refer to Appendix S27 for photographs of the site.

- A diagonal crack was noted across the entire road along an approximately 65 m segment of the highway. There was a slight bump felt when driving across the crack, with the portion of the road to the east of the crack very subtly downdropped relative to the west side. Photos S27-1 to S27-3 in Appendix S27 show views of the highway and cracking.
- The crack had previously been sealed, but was open at the time of the site inspection with a maximum aperture in the order of 25 to 50 mm.
- This site is located near the Crowsnest River channel and there is a gravel pit located in the area to the north of the site. This suggests that the native soils underlying the site are gravelly and cobbly. The embankment fill slope on the south side of the highway

appeared to consist of gravelly and cobbly soil. There were no visible signs of landslide disturbance or deformation on the embankment fill slope.

- A Telus pedestal was noted on the slope south of the highway, a few metres upslope of the fenceline.

### **Discussion**

The orientation of the diagonal crack in the road surface suggests that the road embankment is being damaged by landslide movement down towards the south/southeast. However, the magnitude of dropdown of the portion of the road east of the crack was very minor to negligible at the time of the inspection and there was no other visual evidence of landslide movement in the area.

### **Assessment and Risk Level**

Based on the visual observations from the site inspection, it appears that there may be slow, ongoing slope movement as described above. However, the damage to the road surface to date has been relatively minor. It is also possible that the damage to the road surface is due to differential settlement of the embankment fill, however the age of the highway and the pattern of cracking is not entirely consistent with such a scenario.

In any case, the damage to the road surface appears to have been manageable to date as a maintenance issue.

Based on the above, AMEC recommends the following Risk Level factors for this site:

- Probability Factor of 5 to reflect the apparent active movement or settlement but at a slow rate and with an indeterminate movement pattern.
- Consequence Factor of 1.5 to reflect the minor damage to date to the pavement surface that appears to be manageable as a maintenance issue without affecting the use of the roadway.

Therefore, the recommended Risk Level for this site is 7.5.

### **Recommendations**

As discussed on site, it is recommended that this site be included on the list of annual site inspections in 2008 in order to take another look at the site conditions and estimate if the crack is becoming worse over time and if further work is warranted at this site.

AMEC also understands that AIT is going to check their files regarding this site to see if further relevant information is available.



## 5.0 SUMMARY

A list of the sites, ranked by current recommended Risk Level, is presented in Table A4 in Appendix A for reference. This table also shows:

- Which sites have been recommended for further assessment (e.g. site investigation).
- Which sites have been recommended for repair work, and whether or not the recommended repair work is pending.

## 6.0 CLOSURE

This report has been prepared for the exclusive use of Alberta Infrastructure and Transportation for the specific project described herein. Any use which a third party makes of this report, or any reliance on or decisions to be made based on it are the responsibility of such third parties. AMEC Earth & Environmental, a division of AMEC Americas Limited cannot accept responsibility for such damages, if any, suffered by any third party as a result of decisions made or actions based on this report. This report has been prepared in accordance with accepted geotechnical engineering practices. No other warranty, expressed or implied, is made.

We trust that this meets your needs at this time. Please contact the undersigned if you have any questions or require any further information.

Respectfully Submitted,

**AMEC Earth & Environmental,  
a division of AMEC Americas Limited**

Andrew Bidwell, M.Eng., P.Eng.  
Associate Geological Engineer

APEGGA Permit To Practice No. P-04546

Reviewed by:

Pete Barlow, M.Sc., P.Eng.  
Principal Geotechnical Engineer

## **APPENDIX A**

### **Tables**

**Table A1 – Geohazard Risk Level Factors**

Risk Level = (Probability Factor, PF) x (Consequence Factor, CF)	
Probability Factor (ranked on a scale of 1 to 20)	
1	Inactive, very low probability of slide occurrence.
3	Inactive, low probability of remobilization.
5	Inactive, moderate probability of remobilization, uncertainty level moderate, or active but very slow rate of movement or indeterminate movement pattern.
7	Inactive, high probability of remobilization or additional hazards, uncertainty level high, or active with perceptible movement rate and defined zone(s) of movement.
9	Active with moderate steady, or decreasing, rate of ongoing movement.
11	Active with moderate but increasing rate of movement.
13	Active with high rate of movement, steady or increasing.
15	Active with high rate of movement with additional hazards.
20	Catastrophic slide is occurring.
Consequence Factor (ranked on a scale of 1 to 10)	
1	Shallow cut slope where slide may spill into ditches or fills where slide does not impact pavement, minor consequence of failure, no immediate impact to driver safety, maintenance issue.
2	Moderate fills and cuts, not including bridge approach fill or headslopes, loss of portion of the roadway or slide onto road possible, small volume. Shallow fills where private land, waterbodies or structures may be impacted. Slides affecting use of roadways and safety of motorists, but not requiring closure of the roadway. Potential rock fall hazard sites.
4	Fills and cuts associated with bridges, intersectional treatments, culverts and other structures, high fills, deep cuts, historic rock fall hazards areas. Sites where partial closure of the road or significant detours would be a direct and unavoidable result of a slide occurrence.
6	Sites where closure of the road would be a direct and unavoidable result of a slide occurrence.
10	Sites where the safety of public and significant loss of infrastructure facilities or privately owned structures will occur if a slide occurs. Sites where rapid mobilization of large scale slide is possible.

**Table A2 – Rock Fall Risk Level Factors**

Probability Factor – Rock Falls  
(For Each Rock Cut or Rock Slope)

Weight	Description
1	Inactive, very low probability of fall occurrence.
3	Inactive, low probability of fall occurrence.
5	Inactive, moderate probability of fall occurrence.
7	Inactive, high probability of fall occurrence (e.g. seasonal, following freeze/thaw cycles) and/or a fall has occurred in the historic past.
9	Active, falls occur after exceptional weather (e.g. the melting of greater than average snow accumulations or exceptionally intense precipitation), fall frequency is in the order of once a decade.
11	Active, one or two falls occur each year triggered by annually recurring weather conditions.
13	Active, several falls occur each year and/or the frequency of falls is increasing in comparison to equivalent time periods in previous years.
15	Active, many falls occur each year and/or the area producing rock falls is expanding. Ongoing or persistent rock falls during specific times of the year.
20	Active, a large volume of rock is surrounded by open cracks. Toppling or sliding of the displacing mass is accelerating. Sites where rapid movement of a large fall is possible.

Consequence Factor – Rock Falls  
(For Each Rock Cut or Rock Slope)

Weight	Description
1	Rock fall contained by ditch if cleaned as required to maintain capacity.
2	Rock fall onto roadway removable by maintenance crews by hand or with shovels. Road closure not required. Minor damage to the road surface that can be repaired during annual patching and sealing of the road. Minor to no damage to vehicles being struck by falling rocks or striking rocks deposited onto road.
3	Rock fall onto road that could damage a vehicle (e.g. flat tire, dent body of vehicle). Rocks bounce or roll onto the road surface but likely not with a trajectory that would pass through the windows or windshield of a passing vehicle.
4	Individual rocks or the total volume of rocks deposited on the road large enough to:  Damage vehicles or cause accidents if struck by traffic or damage vehicles and injure occupants if they strike a moving vehicle. <ul style="list-style-type: none"> <li>o Cause partial closure of the road or require a detour lane prior to cleanup.</li> </ul> Damage to the road surface may require temporary repair in order to re-open road.
6	Individual rocks or the total volume of rocks deposited on the road large enough to: <ul style="list-style-type: none"> <li>o Damage/destroy vehicles and severely injure occupants if struck by traffic or damage/destroy vehicles and severely injure/kill occupants if they strike a moving vehicle.</li> <li>o Cause complete closure of the road, with a rough detour/diversion possible within hours to days.</li> <li>o Require days to weeks required to restore the road to normal service.</li> </ul> Possibly significant damage to the road surface that requires immediate repair.
8	Same as weighting of 6, but with several days required to develop a rough detour/diversion around the rockfall site.
10	Individual rocks or the total volume of rocks deposited on the road large enough to: <ul style="list-style-type: none"> <li>o Damage/destroy vehicles and severely injure occupants if struck by traffic.</li> <li>o Bury vehicles if they strike a moving vehicle.</li> <li>o Cause complete closure of the road, with a temporary, rough detour or diversion possible in days to weeks.</li> <li>o Require complete reconstruction or rerouting of the road after the rockfall.</li> </ul>

**Table A3 – Debris Flow Risk Level Factors**

**Probability Factor – Debris Flows**  
(For Each Fan)


<b>Weight</b>	<b>Description</b>
1	Inactive, very low probability of a flow. No historical or current visual evidence of debris flow activity.
3	Inactive, low probability of a flow.
5	Inactive, moderate probability of a flow based on channel morphology and presence of debris in the potential source zone.
7	Inactive, high probability of a flow; a flow has occurred in the historic past and/or debris buildup in the channel/source area is considered to be ongoing.
9	Debris accumulation normally present in the source area. Fan is considered to be active, with flows occurring after the melting of an exceptional snow accumulation or an exceptionally intense rainfall.
11	Active, one or two flows per year triggered by annually recurring weather conditions.
13	Active, several flows each year.
15	Active, many flows each year, the area producing flows is expanding.
20	Active, a large volume of debris is impounding a large and rising reservoir of water upstream. Overtopping and dam-break is expected.

**Consequence Factor – Debris Flows**  
(For Each Fan)

<b>Weight</b>	<b>Description</b>
1	Debris flow contained by the ditch or able to be conveyed past the road alignment via a sufficiently sized culvert or clear span bridge.
2	Debris flow onto roadway easily removable by maintenance crews. No damage to the road surface. Road closure not required and/or road still passable without damage to vehicles provided reduced speed limit established.
4	Partial closure of the road or significant detours would result from a debris flow.  Debris flow onto roadway that requires partial closure of the road or significant detours while maintenance crew uses heavy equipment to clear debris and restore road surface. Damage to the road surface possible.
6	Complete closure of the road would result from debris flow while maintenance crew uses heavy equipment to clear the roadway and/or remove debris flow deposits plugging culvert or ditch. Geotechnical inspection required to assess post-event stability of road fills. Damage to the road surface likely.
10	Sites where the safety of the public is threatened by a debris flow, where there will be significant loss of infrastructural facilities or privately-owned structures if a flow occurs.

**Table A4 – Summary of Recommended Risk Levels for Southern Region Sites**

Site	Recommended Risk Level Value		Recommendations		
	Current	2006	Annual Inspection In 2008	Further Assessment	Design and Repair or Maintenance Work, With Notes On Schedule Where Applicable
S15 – Crowsnest Lake Rockfall Barrier	90	15	Yes	No	Repairs to net required ASAP.
S14 – Bellevue Sites (Potential sinkhole site)	72	72	No	Borehole drilling to follow-up and supplement 2004 GPR survey.	Nothing planned. To be confirmed once borehole information available.
S12 – Spray Lakes Road	54	63	Yes	No	Develop list of repair options for AIT review and decision.
S26 – Highway 41 - Elkwater	52	n/a	Yes	Boreholes to assess applicability of horizontal drains to reduce landslide movement.	Horizontal drain design, pending information from boreholes. Boreholes not scheduled yet. Ongoing road maintenance as required.
S19 – Highway 40 – King Creek (worst case scenario)	50	50	Yes	No	Design/cost estimate for secondary culvert, for AIT review and decision.
S2 – Priddis	45	45	Yes	New piezometers.	Maintenance of road surface as required.
S17 – Highway 40 – Mount Baldy Rock Cut - East Cut Slope	45	45	Yes	No	Scaling – as soon as practical. Ditch cleaning – ongoing.
S18 – Highway 40 – Galatea Creek Through-Cut - East Cut Slope	45	45	Yes	No	Ditch cleaning – ongoing. Increase capacity of East Ditch (if possible while maintaining clear width requirements).
S20 – Highway 541 – Highwood House Rock Cut	45	45	Yes	Track and assess required effort for ditch cleaning to verify if it is cost-effective vs. other measures.	Ditch cleaning – ongoing.
S10 – Highway 762 S10(A)	44	44	Yes	No	Develop list of repair options for AIT review and decision.
S21 – Highway 541 – Highwood Base Road Creek	33	33	Yes	No	Excavate and haul away debris from upslope side of road. Clean out debris from existing culvert or install second culvert.
S1 – Jumpingpound Creek	30	40	Yes	No	Surface drainage improvements and apply creek bank erosion protection measures.
S23 – Highway 507:02 – East Of Mill Creek	30	30	Yes	No	Excavation to maintain south ditch capacity – if required. Maintenance work if/when required.
S7 – Millarville	30	24	Yes	Install SI's and piezometer in new cracking area. Locate and mark shear key drain outlet for future visual monitoring.	Nothing planned. To be confirmed once new instrument data available.
S3 – Cochrane	27	27	Yes	No	Repairs to ditch berm. Develop list of repair options for AIT review and decision.
S24 – Highway 507 – Westbound Lane Site	27	27	No (unless recommended further assessment work performed)	Boreholes to check subsurface conditions and investigate causes of damage to road surface.	Depends on findings from boreholes, otherwise continue with road surface maintenance as required.
S10 – Highway 762 S10(C)	27	n/a	Yes	Overexcavate existing sinkhole in west embankment slope to further assess its cause.	Nothing planned. To be confirmed once further assessment completed.
S8 – Fisher Creek	24	32	Yes	No	Shear key design previously completed. Defer repair work until if/when more significant damage occurs.
S28 – Highway 3A At Range Road 2-2A	24	n/a	Yes	Airphoto review, site survey, and borehole drilling/instrumentation to characterize slope instability.	Design work based on further assessment data. In the meantime, road surface maintenance as required.
S5 – Chin Coulee	20	25	Yes	No	Install soil nails to stabilize downslope shoulder of road.
S22 – Highway 762 "S" Curve	20	10	Yes	No	Maintain road surface as necessary. Develop list of repair options for AIT review and decision.
S19 – Highway 40 – King Creek ('typical' year)	10	n/a	Yes	No	Design/cost estimate for secondary culvert, for AIT review and decision.
S4 – Willow Creek	18	18	Yes	No	Repair work to be tendered, late 2007. Planned to be completed in spring 2008.
S24 – Highway 507 – Eastbound Lane Site	18	18	No	No	Road surface maintenance as required.
S14 – Bellevue Sites (Rock cut site)	15	15	No	No	n/a
S18 – Highway 40 – Galatea Creek Through-Cut - West Cut Slope	12	12	Yes	No	Ditch cleaning in conjunction with east ditch at this site.
S27 – Highway 3 – Windmill	7.5	n/a	Yes	No	Nothing planned.
S16 – Chain Lakes Site	5	n/a	Yes	Instrument readings in 2008.	n/a
S25 – Highway 3 – Monarch	5	n/a	Yes	Not recommended.	Road surface maintenance as required.
S29 – Highway 1 – Seven Persons Creek	5	n/a	Yes	No	n/a



**NOTES:**

1. AFTER RITCHIE (1963), AS SHOWN IN TRANSPORTATION RESEARCH BOARD SPECIAL REPORT 247 (1996).

**amec** Earth & Environmental

PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT


TITLE: ROCKFALL CATCHMENT DITCH SIZING CHART

DATE: AUGUST 2007	JOB No.: CG25263	CAD FILE: 25263X04.dwg	FIGURE No.: FIGURE A1	REV. A
-------------------	------------------	------------------------	-----------------------	--------

**Alberta**  
INFRASTRUCTURE AND  
TRANSPORTATION

**APPENDIX S27**  
**Highway 3 – Windmill**





SCALE



**amec** Earth & Environmental

CLIENT:



PROJECT: **SOUTHERN REGION GEOHAZARD ASSESSMENT**

TITLE: **LOCATION PLAN  
S27 - HIGHWAY 3 - WINDMILL**

DATE: <b>AUGUST 2007</b>	JOB No.: <b>CG25263</b>	CAD FILE: <b>25263L01.dwg</b>	FIGURE No.: <b>S27-1</b>	REV. <b>A</b>
-----------------------------	----------------------------	----------------------------------	-----------------------------	------------------





**Photo S27-1– June 2007** (upper left)  
Facing west along the highway with the diagonal crack visible across the entire road width.




**Photo S27-2– June 2007** (upper right)  
Facing east across the very west end of the cracking area.



**Photo S27-3– June 2007** (lower left)  
Closer view, facing east, of the east end of the cracking area. At the time of the June 2007 site inspection the portion of the highway to the east of the crack was subtly downdropped relative to the west.





SCALE



**amec** Earth & Environmental

CLIENT:



PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT

TITLE: **LOCATION PLAN**  
**S27 - HIGHWAY 3 - WINDMILL**

DATE: <b>AUGUST 2007</b>	JOB No.: <b>CG25263</b>	CAD FILE: <b>25263L01.dwg</b>	FIGURE No.: <b>S27-1</b>	REV. <b>A</b>
-----------------------------	----------------------------	----------------------------------	-----------------------------	------------------





**Photo S27-1– June 2007** (upper left)  
Facing west along the highway with the diagonal crack visible across the entire road width.



**Photo S27-2– June 2007** (upper right)  
Facing east across the very west end of the cracking area.



**Photo S27-3– June 2007** (lower left)  
Closer view, facing east, of the east end of the cracking area. At the time of the June 2007 site inspection the portion of the highway to the east of the crack was subtly down-dropped relative to the west.