

SITE NUMBER AND NAME: S048 Castle Back Slope Failures		HIGHWAY & KM: 3:04, 23.708	PREVIOUS INSPECTION DATE: June 8, 2021	INSPECTION DATE: May 8, 2023
LEGAL DESCRIPTION: 15/06-12-007-01 W5M	NAD 83 COORDINATES: UTM Northing Easting 11 5492157 715695		RISK ASSESMENT: PF: 9 CF: 3 TOTAL: 27	
AVERAGE ANNUAL DAILY TRAFFIC (AADT): 4,100 (west), 4,340 (east), (Ref. No. 78050)			CONTRACTOR MAINTENANCE AREA (CMA): 26	

SUMMARY OF SITE INSTRUMENTATION: None present LAST READING DATE: N/A	INSPECTED BY: Chris Grapel (KCB) Peter Roy (KCB) Alex Frotten (AT) Roger Skirrow (AT)
PRIMARY SITE ISSUE: Multiple slope failures on the south bank of the highway into the ditch extending up to 4 m onto private land. The slope failures are coalescing to form larger backslope failure areas and toe rolls are blocking the ditch.	
APPROXIMATE DIMENSIONS: Approximately 200 m length of 6 m to 10 m high back slope. The slope is approximately 3H:1V.	
DATE OF ANY REMEDIAL ACTION: No recent remedial measures have been undertaken.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X	Failures are not affecting the highway.		X
Slope Movement	X		Slope above the highway has failed in multiple locations.		X
Erosion	X		Some erosion of the failed material in the ditch.		X
Seepage	X		Some moist soil in the slide areas.		X
Culvert Distress		X	None observed.		X

COMMENTS
During the 2023 inspection, the lateral extents of the slope failure appeared similar to 2021. In the slide zones, the near vertical upper back scarp is up to 1.8 m high. Tension cracking near the crest indicates ongoing slope movement and slide retrogression. Failure zones are coalescing, and will eventually result in one long failure zone after which further retrogression into private land may occur.
Slide zones are located over approximately 200 m length on the south side of the highway. Slides appear to be a result of groundwater and precipitation leading to saturation of the slope south of the highway. The north-facing aspect of the slide will decrease evapo-transpiration from the slope surface and promote a longer duration of snow cover in the spring. The highest stable slope is approximately 5.5 m, located at the east end of the north facing backslope.
The field located at the top of the slope failure is mostly graded towards the river and crop furrows are parallel to the fence line meaning that surface runoff is likely to drain away from the highway.
Zones of accumulation at the toe of the slide are blocking the ditch over the length of the failure. Areas of ponded water were noted along the length of the ditch.

A Shaw utility line is located approximately a quarter of the way up the slope. The utility cable is marked with a sign.

The south-facing backslope north of the highway is stable.

Recommended Mitigation Measures:

Short Term:

- The drainage ditch should be regraded to allow for positive surface water drainage, this will require the removal of the slide toe materials from the ditch. Materials removed should be kept to the minimum required to re-establish drainage without initiating additional slope movements.

Long Term:

- Flatten the slope to 4H:1V or 5H:1V, which would require moving the fence line back on the slope crest. A preliminary design should be prepared to assess slope flattening and the area of land required should be assessed. KCB could prepare the preliminary design without investigation, with AT putting the investigation costs into land purchase. AT land agents should contact the owner of the land at the crest of the backslope and start discussions on land procurement.
- Material excavated during slope flattening could be stockpiled in low area to the southwest of the site, levelling the area for possible future use by the farmer. The stockpile/fill placement should consider the potential for destabilizing the Oldman River slope near the Hwy 3 bridge.


This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.






Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

- (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
- (ii) The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
- (iii) The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
- (iv) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.
- (v) This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

<p>Peter Roy, P.Eng. Civil Engineer</p>	
---	--



Legend

-  GPS Waypoint (May 8, 2023)
-  GPS Track (May 8, 2023)
-  Flow Direction
-  Scarp
-  Fence

NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM ZONE 11N
 3. IMAGE SOURCE: ESRI, MAXAR, EARTHSTAR GEOGRAPHICS AND THE GIS USER COMMUNITY.

CLIENT




PROJECT SOUTHERN REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan S048 - Castle Back Slope Failures Hwy 3:04, km 23.708		
SCALE 1:2,500	PROJECT No. A05116A03	FIG No. 1

Photo 1 Toe rolls from formerly separate slope failure zones coalescing and blocking the ditch. Photo was taken facing southeast on May 10, 2023.



Photo 2 Toe rolls coalescing and blocking the ditch. Photo was taken facing west on May 10, 2023.



Photo 3 Slope on the south side of the road. Photo was taken facing west on May 10, 2023.

