

SITE NUMBER AND NAME: S002 Priddis		HIGHWAY & KM: 22:14, 12.595	PREVIOUS INSPECTION DATE: June 9, 2020	INSPECTION DATE: May 9, 2023
LEGAL DESCRIPTION: 01-34-022-04 W5M	NAD 83 COORDINATES: UTM Northing Easting 11 5642606 678005		RISK ASSESSMENT: PF: 7 CF: 4 TOTAL: 28	
AVERAGE ANNUAL DAILY TRAFFIC: 2520 (east) & 2520 (west) (Ref. No. 62187)			CONTRACTOR MAINTENANCE AREA (CMA): 27	

SUMMARY OF SITE INSTRUMENTATION: 2 functioning slope inclinometers (SI) SI #9 and SI #11 and 3 active vibrating wire piezometers (VWPs). LAST READING DATE: June 2023	INSPECTED BY: Chris Grapel (KCB) Peter Roy (KCB) Renato Macciotta (U of A) Roger Skirrow (AT) Alex Frotten (AT) Maury Siddons (AT)
---	--

PRIMARY SITE ISSUE: Pavement cracking at the northwest edge of the highway caused by continued slope movement downslope of a concrete pile wall (unknown date of construction and unknown design details).

APPROXIMATE DIMENSIONS: Landslide zone affecting highway is approximately 90 m long. Slope varies from 3H:1V on the upper half of the slope and 5H:1V on the lower half of the slope. Embankment slope approximately 15 m high.

DATE OF ANY REMEDIAL ACTION: A concrete pile wall was installed along the northwest shoulder of highway in 1992, to stabilize the highway against the ongoing landslide movement. Additionally, a row of gravel columns was installed on the upslope, southeast, side of the highway and two pumps placed in the gravel columns with a water-level-activated switch to turn the pumps on. The pumps are permanently installed but are turned off during winter months. As-built information for repairs is not available. Last pavement overlay was 7 years ago. Patching of the cracking has periodically been completed by the maintenance contractor.

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Cracking and settlement of the north shoulder of the road surface was observed, between the guard rail and existing pile wall location. Depth of settlement around piles appears to be about the same in 2020. The pavement cracking at the east end of the slide extends the full width of the highway.		X
Slope Movement	X		There is an active slope failure to the north of the highway in front of the pile wall. Dip in guard rail.	X	
Erosion	X		None noted. Vegetation cover was continuous over the slide area.		X
Seepage	X		Seepage at the toe of the slope, from buried culvert.		X
Culvert Distress	X		Buried culvert appears to be discharging water into small pond at the toe of the slope.		X

COMMENTS
<p>Pavement cracks were patched a few years ago after the previous inspection in 2020, cracking has come though the patches. Cracking should be repaired by the maintenance contractor through patching. Cracking at the east extent of the slide across the highway surface appears unchanged since the previous inspection in 2020.</p>
<p>At the time of the site visit, the pumps in the gravel columns were operational with active discharge. The pumps are permanently installed in the wells and get turned on and off for winter. Pondered water was observed in the upslope ditch, adjacent to the discharge lines from the groundwater pumps.</p>
<p>No obvious increase in slope cracking was noted. Guard rail deflection appears unchanged from the 2020 site visit.</p>
<p>Seepage was noted at the tree line approximately in the centre of the slide upslope of a buried culvert. Seepage reports to a drainage channel, which contains standing water.</p>
<p>There is a culvert to the east of the slide zone which was active and flowing during the site visit. The culvert channel is overgrown and partly filled with sediment. A ditch plug diverts water into this culvert.</p>
<p>New instrumentation covers should be installed on the SIs adjacent to the roadway. The current covers have holes in them that allows sediment to migrate into the instruments, making reading difficult and impacting the ability to accurately read instruments.</p>
<p>The thickness of asphalt on the north shoulder is around 500 mm thick. AT pavement LIDAR could be used to monitor changes in the road surface over several years.</p>
<p>It is understood that Highway 22 at this location is to be twinned at some point in the future.</p>
<p>The nature of the reinforced pile wall should be investigated with the use of wet rotary diamond drilling techniques to identify how deep the piles are. Geophysical methods could be used to assess pile depths and check for the presence of rebar. At least three piles should be located and investigated. The assessment should include drilling boreholes downslope of the pile wall to install two slope inclinometers to allow assessment of the depth of movement downslope of the pile wall against the depth of the pile wall. The impact of turning off the groundwater pumps in the winter should be assessed by placing level loggers in the pump wells and reviewing the data in the spring when the pumps are turned back on.</p>




This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

- (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
- (ii) The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
- (iii) The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
- (iv) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.
- (v) This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

Peter Roy, P.Eng.
Civil Engineer



- Legend**
- ▣ Slope Inclinometer (SI)
 - ⊗ Vibrating Wire Piezometer (VW)
 - △ GPS Waypoint (May 8, 2023)
 - GPS Track (May 8, 2023)
 - Gravel Column
 - ⊕ Pile Wall

NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM ZONE 11N
 3. IMAGE SOURCE: ESRI, MAXAR, EARTHSTAR GEOGRAPHICS AND THE GIS USER COMMUNITY.
 4. STRIKETHROUGH INDICATES INSTRUMENT IS INACTIVE.

CLIENT

PROJECT SOUTHERN REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan S002 - Priddis Hwy 22:14, km 12.95		
SCALE 1:1,000	PROJECT No. A05116A03	FIG No. 1

Photo 1 Pavement distress at the location of the pile wall. Photo taken facing west on May 9, 2023.



Photo 2 Cracking at the east extent of the slide on the highway. Photo taken facing west on May 9, 2023.



Photo 3 South ditch with pumps shown. Photo taken facing east on May 9, 2023.



Photo 4 Cracking and hole in pavement at pile wall location. Photo taken facing east May 9, 2023.



Photo 5 Embankment slope north of the highway. Photo taken facing east on May 9, 2023.



Photo 6 Ponded water at the toe of the slope. Photo taken facing south on May 9, 2023.

