

SOUTHERN REGION GRMP SITE INSPECTION FORM



SITE NUMBER AND NAME	E: HIGHWAY & KM:	PREVIOUS	INSPECTION DATE:
S005 Chin Coulee	36:02, 37.101	INSPECTION DATE:	May 11 2023
		May 9, 2019	May 11, 2020
LEGAL DESCRIPTION:NAD 83 COORDINATES:10-36-007-17 W4MUTM Northing Easting115495465414771		RISK ASSESMENT: PF: 9 CF: 2 TOTAL: 18	
AVERAGE ANNUAL DAIL 720 (north), 900 (south), Re	/ TRAFFIC (AADT): ef No. (70000182)	CONTRACTOR MAINTENANCE AREA (CMA): 24	

SUMMARY OF SITE INSTRUMENTATION:	INSPECTED BY: Peter Rov (KCB)
Two slope inclinometers and four vibrating wire piezometers, installed after the 2016 highway realignment.	Alex Frotten (AT) Roger Skirrow (AT)
LAST READING DATE: June 2023	
PRIMARY SITE ISSUE: Large deep seated, retrogressive, translational earth slide. H road surface due to highway realignment.	lead scarp no longer affecting
APPROXIMATE DIMENSIONS: Overall slope is approximately 100 m above Chin Co has a slope of approximately 3H:1V from head scarp to reservoir level.	ulee Reservoir and overall
DATE OF ANY REMEDIAL ACTION: Highway realignment completed in fall 2016. The	he highway shoulder is now

DATE OF ANY REMEDIAL ACTION: Highway realignment completed in fall 2016. The highway shoulder is now located approximately 10 m north of the extents of previous asphalt cracking. Ditch constructed on south side of highway. Slide area at the top of the embankment was graded. Previously constructed masonry block wall removed.

ITEM		ITION S	N DESCRIPTION AND LOCATION		NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO	
Pavement Distress		Х	None since realignment.		Х	
Slope Movement	х		Previous head scarp at road surface graded. Movement ongoing downslope.		Х	
Erosion	Х		Erosion downslope, not near highway		Х	
Seepage					Х	
Culvert Distress		Х			Х	

COMMENTS

Visit site once per contract. The longer-term plan for this site is potentially to reroute the road several hundred metres to the west as part of a project related to potential expansion of the Chin Coulee reservoir and relocation of the Hwy 36 bridge.

There are 10 geocubes installed at the site for slide monitoring. No visible difference was observed to the slide when compared with the 2019 inspection but the geocube data suggests general deformation in a southernly direction, possibly with an element of toe movement in a southeasterly direction. The largest movement noted in the geocube data was from SM22-04, located at the crest of the slope to the east, which was estimated to be approximately 193 mm in the downslope direction and 110 mm vertically (between May 2022 and August 2023).





Cumulative movements during the monitoring period were estimated as between 1 mm and 33 mm (horizontally) and 3 mm and 12 mm (vertically), across the other geocubes.

The slide is large with multiple back scarps and reverse grabens. The size of this slide infers a deep-seated translational failure mode on a sub-horizontal weak layer. Toe of slide is below the fluctuating reservoir level, which may influence slide mobilization.

Check dams in ditches have too steep of an upstream slope and may constitute a traffic hazard if a car leaves the highway.

This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

- (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
- (ii) The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
- (iii) The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
- (iv) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.
- (v) This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

Peter Roy, P.Eng. Civil Engineer	





SCALE 1:1 500 PROJECT No. A05116A03 FIG No. 1				
	_	SCALE 1:1,500	PROJECT No. A05116A03	FIG No. 1

Photo 1 Geocube installed at crest of slope between highway and slide area. Photo taken facing east on May 11, 2023.



Photo 2 Slope failure downslope of highway. Photo taken facing southeast on May 11, 2023.





Photo 3 Crest of slope, downslope of highway. Photo taken facing west on May 11, 2023.



Photo 4 Ditch check dams. Photo taken facing west on May 11, 2023.



