

SITE NUMBER AND NAME: S056-I West Gorge Creek Steep Slope Slides		HIGHWAY & KM: 25002:02 7.693	PREVIOUS INSPECTION DATE: May 16, 2022	INSPECTION DATE: May 28, 2024
LEGAL DESCRIPTION: 15-29-019-05 W5M	NAD 83 COORDINATES: UTM Northing Easting 11 5612799 665797		RISK ASSESSMENT: PF: 12 CF: 10 TOTAL: 120	
MONTHLY AVERAGE DAILY TRAFFIC (MADT): May 2024 242 (west) & 232 (east) (Reference No. 55460220)			CONTRACTOR MAINTENANCE AREA (CMA): 27	

SUMMARY OF SITE INSTRUMENTATION: There is no instrumentation at the S056-I site. LAST READING DATE: N/A	INSPECTED BY: Chris Grapel (KCB) Peter Roy (KCB) Renato Macciotta (U of A) Alex Frotten (TEC) Kristen Tappenden (TEC) Maury Siddons (TEC)
---	---

PRIMARY SITE ISSUE: Slope failure on the south side of the highway due to surface runoff erosion and groundwater. The highway is located at the crest of a steep valley slope above Sheep Creek River. The southern ditch has been undermined and is draining directly into the slide zone. Head scarp has reached the south edge of the highway.

APPROXIMATE DIMENSIONS: Head scarp is approximately 15 m wide at the crest of a 40 m to 50 m high slope above Sheep River. Approximately 1/3 of the way down the slope, the failure area narrows to a 3 m to 5 m wide erosion gully.

DATE OF ANY REMEDIAL ACTION: None

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Head scarp has started to undermine the pavement		X
Slope Movement	X		Slope failure due to ongoing erosion from surface water runoff		X
Erosion	X		Slope erosion due to surface water runoff from the south (eastbound) ditch into slide area	X	
Seepage	X		Groundwater seepage has been observed approximately 3 m down the slope on west side	X	
Culvert Distress		X	N/A – none observed		X

COMMENTS

Steep slope at approximately 2H:1V, with no vegetative cover in the slide area. The highway ditch on the right (west) flank of the slide is draining directly onto the slide area. The slope failure will continue to encroach on the highway surface and guard rail with continued erosion due to the ditch discharge.


A seepage zone was observed during the 2024 inspection, approximately 3 m below the west ditch.

Between the 2022 and 2024 inspection, the slope failure has continued to expand to the west (upslope) and vegetation is falling into the erosion feature. In addition to expanding westwards, the overall slope of the erosion feature is flattening in the upper section as the feature deepens and ongoing erosion continues to remove sediment. Erosion has exposed a sedimentary rock ledge on the west side.

The back scarp has retrogressed to the south edge of highway and the guardrail continues to be undermined. No

deflection of the guardrail was noted.
Slope erosion appears to be depositing an alluvial fan in the Sheep River.
There is a wooden stake and a rock painted orange present upstream of the right flank used to estimate the gully retrogression. At the time of the 2023 inspection, the wooden stake was 1.7 m from the edge of the right flank (Photo 1), which is the same measurement as in 2022.
During the 2020 inspection, tension cracking and slumping was first observed on the left (east) flank of the slope failure. Between the 2021 and 2022 inspections, the ground surface appears to have dropped approximately 0.30 m and a tree had fallen down the slope. There was minimal change noted in this area during the 2024 inspection. The area is expected to eventually fail into the erosion feature downslope, enlarging the disturbed area.
The ongoing toe erosion from the river and surface water runoff from the highway ditch are causing the erosion feature to enlarge and will eventually lead to further undermining of the pavement, surface cracking, and a dip that will require extensive repairs.
<p>Maintenance/Repair/Monitoring Recommendations:</p> <ul style="list-style-type: none"> • The surface water flow into the slide area from the south (eastbound) ditch should be diverted away from the slide area. A cross culvert could divert flow beneath the highway into the north (westbound) ditch. • The slope could be stabilized using either geogrid reinforced granular fill with a timber crib wall, a lock block retaining wall, or a gabion basket wall constructed at the toe of the slide zone on stable ground. A repair design is in progress and this site is tentatively scheduled for construction in 2025.
<p>This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation and Economic Corridors (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.</p> <p>KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.</p> <p>Use of or reliance upon this instrument of service by the Client is subject to the following conditions:</p> <ol style="list-style-type: none"> (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report. (ii) The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time. (iii) The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information. (iv) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report. (v) This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

<p>Peter Roy, P.Eng. Civil Engineer</p>	
---	--



- Legend**
- Flow Direction
 - Main Scarp

NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM ZONE 11N
 3. IMAGE SOURCE: MAXAR 2024

CLIENT

PROJECT		
SOUTHERN REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE		
Site Plan		
S056-1 - West of Gorge Creek Steep Slope Slides Hwy 25002:02, km 7.693		
SCALE	PROJECT No.	FIG No.
1:1,500	A05116A03	1



Photo 1 Failure area located on the downslope side of Sheep River Road. Photo taken May 28, 2024, facing east.



Photo 2 View from highway of the erosion gully, facing downslope. An alluvial fan is forming in the Sheep River due to ongoing erosion. Photo taken May 28, 2024, facing south.



Photo 3 The south (eastbound) ditch is diverting flows into failure area. A painted wooden stake is approximately 1.7 m from the edge of the right (west) flank. Photo taken May 28, 2024, facing west.



Photo 4 Failure of slope close to the shoulder of the eastbound lane, undermining guardrail post. Photo taken May 28, 2024, facing southwest.

