

SITE NUMBER AND NAME: S041 East Coulee Slide		HIGHWAY & KM: 564:10, 32.353	PREVIOUS INSPECTION DATE: June 10, 2020	INSPECTION DATE: June 24, 2021
LEGAL DESCRIPTION: 04-21-27-18 W4M	NAD 83 COORDINATES: UTM Northing Easting 12 5686022 396402		RISK ASSESSMENT: PF: 9 CF: 5 TOTAL: 45	
AVERAGE ANNUAL DAILY TRAFFIC (AADT): 130 (south), (Reference No. 113210)			CONTRACT MAINTENANCE AREA (CMA): 521	

SUMMARY OF SITE INSTRUMENTATION: No functional instruments. LAST READING DATE: Unknown	INSPECTED BY: Chris Gräpel (KCB) James Lyons (KCB) Roger Skirrow (AT) Tony Penney (AT)
--	--

PRIMARY SITE ISSUE: A natural slope failure on the west side (southbound lane) of Hwy 564 that was triggered by highway widening (i.e., cut and fill placement) in 1979.

APPROXIMATE DIMENSIONS: The slide is approximately 120 m wide at the crest and 250 m wide near the mid-slope. Below where the slope was previous repaired, the slope is approximately 50 m high sloped at 3H:1V.

DATE OF ANY REMEDIAL ACTION: 2008: 800 soils nails were launched, and a geosynthetic reinforced toe berm was constructed to support the highway; 2011: the highway was realigned to the south into the upslope ditch.

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Gravel appears to be added to road surface and periodically regraded.	X	
Slope Movement	X		Guardrail continuing to subside. Slide head scarp is outflanking the existing soil nail wall to the northeast.	X	
Erosion	X		Erosion caused by surface water flow (i.e., flow erosion)		X
Seepage		X	None observed		X
Culvert Distress		X			X

COMMENTS

The guardrail appears to have subsided further since the 2020 inspection as the slope below the crest of the highway continues to fail. The top of the guardrail is now below the crest of the road. Note: the severity of guardrail subsidence may be accentuated by additional gravel placement on roadway.

The slide appears to be a translational slide with some rotation that is sliding on a weak layer (depth of weak layer is unknown due to lack of instrumentation data, but a depth of between 6 m and 17 m below ground surface has been estimated based on visual observations).

The downslope crest of the slide tips back towards the highway. Tension cracks observed during 2017 inspection appear to have been filled. Since the 2017 inspection, the slide is starting to outflank the existing soil nail wall to the northeast.

A "Road Narrows – 35 km/hr" sign was installed in the westbound lane at the east end of the site.

Drainage at the site is poor. A shallow ditch exists on the south side of the highway but is periodically filled with gravel during grading. The old geocell in the ditch has also been damaged and buried during grading operations. Where the highway is subsided, surface water from the ditch flows across the highway onto the slide area. Slope movements are likely exacerbated by infiltration of this surface water flow into cracks at the crest of the slide. Erosion is occurring at the culvert outlet northeast of the soil nail reinforced slope.

Candidate repair options for this site are:

Short-Term

- Raising the elevation of the roadway to create a proper ditch on the south side of the highway (would require limited and carefully executed cutting into the existing backslope to create additional width for a ditch) and protect the ditch from being infilled.
- Raise subsided guardrail on north side of highway to prevent motorists from driving over the edge of the slope.

Long-Term

- Installing drainage (e.g., a ditch or culvert) to redirect water away from the slide area using a slope drain with energy dissipater to convey water over the slope and prevent further erosion or saturation of the slide area. A pile wall could be installed to stabilize the road, however the traffic volume may not justify a pile-wall.


This report is an instrument of service of Klohn Crippen Berger Ltd. (KCB). The report has been prepared for the exclusive use of Alberta Transportation (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill, and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

- (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
- (ii) The observations, findings, and conclusions in this report are based on observed factual data and conditions that existed at the time of the work, and should not be relied upon to precisely represent conditions at any other time.
- (iii) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.

Chris Gräpel, M.Eng., P.Eng.
Civil Engineer, Associate



- Legend**
- ▲ GPS Waypoint (June 24, 2021)
 - ~~~~~ Crack
 - ▬▬▬ Scarp
 - Flow Direction

NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM Zone 12N
 3. IMAGE SOURCE: Bing Maps, Microsoft Corporation 2020
 Source date April 3, 2012

CLIENT

Alberta
Government

Klohn Crippen Berger

PROJECT SOUTHERN REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan S041 - East Coulee Slide Hwy 564:10 km, 32.353		
SCALE 1:1,500	PROJECT No. A05116A03	FIG No. 1

Time: 14:14:54 PM
 Date: October 14, 2021
 File: Z:\AUCSY\Alberta\A05116A03\ABT_Southern Region GRMP\400 Drawings\2021\Section B figures\MXD\IS041_21101.mxd

Photo 1 Guardrail has subsided below the surface of the road (red circle). Photo taken facing southwest on June 24, 2021.



Photo 2 Shallow ditch on south side of highway has insufficient capacity to carry surface flows without discharging water across the road onto the slide mass. Photo taken facing southwest on June 24, 2021.



Photo 3 Shallow ditch on south side of highway has insufficient capacity to carry surface flows without discharging water across the road onto the slide mass. Photo taken facing northeast on June 24, 2021.



Photo 4 Surface runoff discharges northwards across the road onto the slide mass due to insufficient capacity in ditch on south side of highway. Photo taken facing southwest on June 24, 2021.

