

SITE NUMBER AND NAME: S040 Dorothy Sinkholes		HIGHWAY & KM: 848:02, 11.507	PREVIOUS INSPECTION DATE: July 10, 2019	INSPECTION DATE: May 31, 2022
LEGAL DESCRIPTION: 06-04-27-17 W4M	NAD 83 COORDINATES: UTM Northing Easting 12 5681315 406434		RISK ASSESSMENT: PF: 8 CF: 4 TOTAL: 32	
AVERAGE ANNUAL DAILY TRAFFIC (AADT): 60 (north) & 180 (south) (Reference No. 116220 & 114210)			CONTRACT MAINTENANCE AREA (CMA): 21	

SUMMARY OF SITE INSTRUMENTATION: There is no instrumentation at this site. LAST READING DATE: N/A	INSPECTED BY: Chris Gräpel (KCB) James Lyons (KCB) Rocky Wang (AT)
PRIMARY SITE ISSUE: Voids/sinkholes forming in dispersive soils and/or bedrock beneath and near the highway surface.	
APPROXIMATE DIMENSIONS: An approximate 500 m long section of the highway is being impacted.	
DATE OF ANY REMEDIAL ACTION: Ongoing – sinkholes close to the highway are backfilled with gravel containing fines; no recent repairs.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Road Surface Distress		X	No sinkholes observed on or near road surface. Gravel surfaced road recently graded.		X
Slope Movement		X	N/A – none observed		X
Erosion	X		Ongoing erosion of dispersive soils creating voids and gullies	X	
Seepage		X	Groundwater seepage		X
Culvert Distress		X	A joint at the CSP culvert outlet is separated		X

COMMENTS
Previous assessments have identified natural groundwater seepage and surface water flow as triggers for void/sinkhole formation. Voids previously observed near the highway are in areas of concentrated drainage (e.g., ditches, and rills and gullies on natural slopes). It is suspected that the ditch does not have the capacity for regularly rainfall events and there have been flows across the highway surface during rainfall events (i.e., heavy, or prolonged rainfall events).
During the 2017 inspection, a sinkhole approximately 1 m in diameter and 1 m deep opened near the middle of the highway after KCB and AT drove over the site (north of WP 512). The area has been repaired by Alberta Transportation (AT) but there may be other soil voids forming beneath the highway surface at the site. A second sinkhole was observed 2 m away from the culvert inlet that is partially undermining the south shoulder of the highway (WP 512).
During the 2018 inspection, a 0.15 m diameter 0.10 m deep sinkhole was observed near the north shoulder of the highway (WP 693). AT marked the location with a survey stake and flagging to warn motorists. A long, shallow sinkhole was discovered along the south shoulder (WP 694) approximately 100 m east of WP 693.
An Unmanned Aerial Vehicle (UAV) flight of the site was completed during the 2022 inspection to take aerial videos/photos (Photo 1 and 2).

An erosion feature was observed in the area inside the hairpin turn.

During the 2022 inspection the back slope was inspected but no sinkholes were observed. No sinkholes were observed along or near the highway surface. However, a large new sinkhole was observed approximately 30 m from the north edge of the highway on the inside of the hairpin curve (Photo 3) (WP 164).

The highway surface was recently graded before the 2022 inspection (Photo 4).

Maintenance/Repair/Monitoring Recommendations:

- Install signage (e.g., speed reduction and hazard markers) to warn motorists of hazard (e.g., potential washouts and collapse features); improve drainage (e.g., increase ditch drainage capacity) to reduce infiltration into underlying dispersive soils and erosion of steep natural slopes; backfill sinkholes and voids as needed; conduct a geotechnical site investigation that includes:
 - conducting a detailed topographic survey of the area (e.g., a LiDAR survey or an unmanned aerial vehicle [UAV] photogrammetry survey), so previous, current and future locations of sinkholes and voids can be plotted relative to the survey data to assess if they correspond to areas with concentrated drainage.
- A risk assessment guideline for dispersive soil sites should be developed.
- The site should be inspected every two-years as part of the Southern Region GRMP Section B inspections.


This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Alberta Transportation (Client) for the specific application to the Southern Region Geohazard Risk Management Program (Contract No. CON0022161) and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.







Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

- (i) The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
- (ii) The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
- (iii) The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
- (iv) KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.
- (v) This report is electronically signed and sealed and its electronic form is considered the original. A printed version of the original can be relied upon as a true copy when supplied by the author or when printed from its original electronic file.

<p>Chris Gräpel, M.Eng., P.Eng. Senior Civil Engineer, Associate</p>	
--	--



Legend

-  GPS Waypoint (May 31, 2022)
-  Sinkholes (AMEC 2016)
-  Sinkholes (KCB, 2016, 2017, 2018)
-  GPS Track (May 31, 2022)
-  Flow Direction
-  Guardrail
-  Fence
-  Culvert



NOTES:
 1. HORIZONTAL DATUM: NAD83
 2. GRID ZONE: UTM ZONE 12N
 3. IMAGE SOURCE: MICROSOFT CORPORATION 2022 MAXAR CNES, DISTRIBUTION AIRBUS DS
 4. APPROXIMATE LOCATIONS OF PREVIOUSLY IDENTIFIED SINKHOLES DERIVED FROM AMEC 2016, FIGURE 1

CLIENT




PROJECT SOUTHERN REGION GEOHAZARD RISK MANAGEMENT PROGRAM		
TITLE Site Plan S040 - Dorothy Sinkholes Hwy 848:02, km 11.507		
SCALE 1:1,250	PROJECT No. A05116A03	FIG No. 1

Inspection Photographs

Photo 1 An aerial photo of the S040 Dorothy Sinkholes site. The erosion on the ditch slope, approximate location of the culvert inlet, and a large new sinkhole (WP 164) are indicated by a red arrow, square, and circle, respectively. The highway was graded shortly before the 2022 inspection. Photo taken May 31, 2022, facing east.



Photo 2 Aerial photo of the north side of the highway at the S040 Dorothy Sinkholes site. There is ongoing erosion of the north slope and the erosion has exposed bedrock at the toe of the slope/ditch bottom. Photo taken May 31, 2022, facing southeast.



Photo 3 Sinkhole observed on the inside of the hairpin curve (location shown in Photo 1) north of the highway (WP 164). Photo taken May 31, 2022, facing north.



Photo 4 The highway was graded shortly before the 2022 site inspection. Photo taken May 31, 2022, facing east.

