



Mid-Hill - Faint crack re-appearing through the new path



Up Hill – Side slope scarp.





Spring at old wood casing well.



Spring flowing into vertical CSP well.