



Photo 1. Up hill general view. Note on the foreground the cracking reappearing on the pavement patched in 2003.



Photo 2. Mid-hill pavement distress.



Photo 3 Scarp and graben feature on the sideslope unchanged.



Photo 4 Collection point at the toe of the slope.
Note the oxidation stain elevation



Photo 5 Backslope collection point, Cleaning the surface drainage holes