



**Photo #1** Water standing inside the Uphill CSP drainage collection manhole (MH#1)



**Photo #2** Water ponding around MH#1



**Photo #3** Open arc-shaped crack at the southern limit of Mid-Hill slope section, looking north



**Photo #4** Dip on the highway SBL bounded by a centerline crack along the Mid-Hill slope section, looking east



**Photo #5** Open arc-shaped crack at the northern limit of Mid-Hill slope section, note dip on highway SBL (looking south)



**Photo #6** Diagonal open crack on the northern limit of highway uphill section, looking west



**Photo #7** Looking inside the downhill drainage collection manhole (MH#2)