



Photo #1 Some water around the Uphill CSP drainage collection manhole (MH#1)



Photo #2 Standing water inside MH#1; note that the drain outlets are completely submerged under water



Photo #3 Open diagonal crack at the southern limit of Mid-Hill slope section (looking north)



Photo #4 Open longitudinal crack within the Mid-Hill slope section (looking north)



Photo #5 Open arc-shaped crack at the northern limit of Mid-Hill slope section (looking north)



Photo #6 Looking south at the dip bounded by the cracks to the south of the speed sign on the highway Mid-Hill slope section



Photo #7 Diagonal and longitudinal open crack in the NBL of the highway within the highway uphill section (looking south)



Photo #8 Diagonal open crack on the northern limit of highway uphill section, looking south



Photo #9 Looking at the metal cover above MH#2 location; note seeping water from below the cover



Photo #10 Looking at MH#2 cover; the manhole was locked by others which made it inaccessible for inspection