



**Photo #1** Looking at natural gully located upslope of drainage collection manhole #1



**Photo #2** Standing water inside MH#1; note that the drain outlets are completely submerged under water



**Photo #3** Open diagonal crack at the southern limit of Mid-Hill slope section (looking north)



**Photo #4** Open longitudinal crack within the Mid-Hill slope section (looking north)





**Photo #5** Open arc-shaped crack at the northern limit of Mid-Hill slope section (looking north)



**Photo #6** Looking south at the dip bounded by the cracks to the south of the speed sign on the highway Mid-Hill slope section



**Photo #7** Diagonal open crack on the northern limit of highway uphill section, looking south