



Photo #1 Looking at natural gully located upslope of drainage collection manhole #1



Photo #2 Standing water inside MH#1



Photo #3 Looking at the manhole filled with cobbles located downslope of MH#1; note the rock filled trench by the manhole.



Photo #4 Open diagonal crack at the southern limit of Mid-Hill slope section (Looking northwest)



Photo #5 Open longitudinal crack within the Mid-Hill slope section
(Looking northwest)



Photo #6 Open longitudinal crack within the Mid-Hill slope section; note the drop across the crack surface (Looking northeast)



Photo #7 Open arc-shaped crack at the northern limit of Mid-Hill slope section
(Looking northwest)



Photo #8 Looking southeast at the dip bounded by the cracks to the south of the speed sign
on the highway Mid-Hill slope section



Photo #9 Looking southeast at a longitudinal crack northwest of the Mid-Hill slope section



Photo #10 Looking inside MH#2