









Well defined ditch on backslope side of highway















Two new unstable areas have appeared with scarps regressing towards the pavement