


SITE NUMBER AND NAME C30 H734:12 Slide		HIGHWAY & KM 40.5	PREVIOUS INSPECTION DATE June 29, 2005	INSPECTION DATE May 16, 2006
LEGAL DESCRIPTION NE19-33-08-W5	NAD 83 COORDINATES N 5,745,805 E 629,740		RISK ASSESMENT PF: 5 CF: 1 TOTAL: 5	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Slope instability at the site was repaired in 2004. Flooding in June 2005 caused significant erosion damage to the area. The erosion was repaired in September 2005 (Ledcor)	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: 2004 & 2005	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion		X			
Seepage					X
Culvert Distress	X		The large diameter HDPE pipes have separated at the upper couplings and require repair under warranty	X	

COMMENTS
Refer to previous inspection and repair report and attached photos
Large diameter HDPE pipe couplings to be repaired.