


SITE NUMBER AND NAME C30 H734:12 Slide		HIGHWAY & KM 40.5	PREVIOUS INSPECTION DATE May 16, 2006	INSPECTION DATE June 26, 2008
LEGAL DESCRIPTION NE19-33-08-W5	NAD 83 COORDINATES N 5,745,805 E 629,740		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Slope instability at the site was repaired in 2004. Flooding in June 2005 caused significant erosion damage to the area. The erosion was repaired in September 2005 (Ledcor)	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: 2004 & 2005	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion		X			
Seepage					X
Culvert Distress	X		Several HDPE pipes have separated at the upper couplings and require repair.	X	

COMMENTS
Refer to previous reports and attached photos.
Separated HDPE pipe couplings to be repaired.