

**Photo 1** Condition of oversized slope drain and subsurface drainage pipes. Subsurface drainage pipes were observed flowing during inspection. The slope was saturated below this point (waypoint 878). Photo taken July 9, 2019 looking south.



**Photo 2** Condition of western slope drain and riprap armouring. Photo taken July 9, 2019 looking northwest.



**Photo 3** Condition of ditch along south side of highway that drains to western slope drain.  
Photo taken July 9, 2019 looking west.



**Photo 4** Photo showing the culvert outlets and riprap armoured stilling basin on south side of highway. Photo taken July 9, 2019 looking northwest.



**Photo 5 Riprap armoured channel downstream of culvert outlets. Photo taken July 9, 2019 looking southwest.**



**Photo 6 Photo showing the location where water is discharging over the river valley slope from the armoured outlet channel (waypoint 879). Photo taken July 9, 2019.**

