



Photo 1 – Looking east at the Slide A site along the north side of the Creek.



Photo 2 – Looking northeast from the Creek up at the slide at Site A in the south highway embankment.



Photo 3 – Looking west along the slide scarp adjacent to the Creek at Site A.



Photo 4 - Looking northwest at a slide lobe of Site A extending close to the highway.



Photo 5 – Looking west along the highway at the crack/dip in the highway above Slide A.



Photo 6 - Looking east along the highway and south embankment Site B. Note the settlement in both the highway and the embankment.



Photo 7 – Looking east at the slide scarp adjacent to the highway in the south embankment of Site B.



Photo 8 - Looking at the surface erosion through the existing erosion control soil covering and ditch barriers on the south embankment of Site B.



Photo 9 – Looking west along the south embankment of Site B. Note the benched hillside in the background and the subsidence near to the highway over the culvert.



Photo 10 - Looking northwest at the culvert outlet area of Site B, Hines Creek, and Site A in the background.



Photo 11 – Looking north up along the south embankment of Site B.



Photo 12 - Looking west along the highway at the dip and cracks of Site B.



Photo 13 – Looking north along the east ditch of the north embankment of Site B.



Photo 14 - Looking south at the culvert inlet area north of the highway at Site B. Note the severe ditch erosion up-gradient of the gabions.