THURBER ENGINEERING LTD.



Photo 1 - View of Highway 690 showing the 2008 ACP patch, looking east.



Photo 2 - View of crack reflecting through 2008 ACP patch, looking northeast.





Photo 3 - View of crack reflecting through 2008 ACP patch, looking southwest.



Photo 4 - View of Highway 690 showing the 2008 ACP patch, looking west.





Photo 5 - View of creek looking east.



Photo 6 - View of creek looking west.