



Photo 1 - View of Highway 690 showing the 2008 ACP patch, looking east.



Photo 2 – View of the crack on the highway and asphalt thickness, looking northeast.



Photo 3 – Increased cracking on pavement looking southwest.



Photo 4 - View of Highway 690 showing the 2008 ACP patch, looking west.



Photo 5 - View of creek looking east.



Photo 6 - View of creek looking west.