



Photo 1 - View of Highway 690 showing the 2008 ACP patch, looking east.



Photo 2 - Increased cracking on pavement looking southwest.





Photo 3 - View of Highway 690 showing the 2008 ACP patch, looking west.



Photo 4 - View of creek looking east.



Photo 5 - View of creek looking west.