



Photo 1 - View of Highway 690 showing the 2011 ACP patch, looking east.



Photo 2 – View of the crack on the highway and asphalt thickness, looking southwest.





Photo 3 - View of Highway 690 showing the 2011 ACP patch, looking west.



Photo 4 – View of asphalt thickness and crack