



Photo 1 - View of Highway 690 showing the 2011 ACP patch, looking east.



Photo 2 – View of the crack and asphalt thickness, looking northeast. The dip in the highway surface can be seen in the centre of the patch



Photo 3 – Looking west at west portion of crack and recent patch.



Photo 4 – Slumping at the culvert outlet on the north side of the highway.