



Photo 1 – Looking east over repaired highway and toe berm.



Photo 2 – Looking at voids around HTSCB on south side of highway at the west end.



Photo 3 – Looking east at small crack at west end of slide area near the end of the HTSCB.



Photo 4 – Looking west at bare area at culvert outlet where possible tension cracks may be forming. Subdrain outlet is just on the far side of the culvert outlet.



Photo 5 – Looking east from lined swale at bare spot between the swale and riprap apron.



Photo 6 – Looking west along lined swale located at the south end of the toe berm.



Photo 7 – Looking east at voids around HTSCB posts and settlement cracking of the pavement at west end of the north barrier located by the outlet of BF72371 culvert.



Photo 8 – Looking at riprap placed over bare ground (no nonwoven fabric below) at east end of north ditch the outlet of BF72371.