

## SOUTHERN REGION GRMP SITE INSPECTION FORM



SITE NUMBER AND NAME: S030 Gabion Wall	HIGHWAY & KM: 742:02, 30.940	PREVIOUS INSPECTION DATE: May 1, 2018	May 7, 2019	
LEGAL DESCRIPTION: 02-25-024-11 W5M	NAD 83 COORDINATES: UTM Northing Easting 11 5658981 611421	RISK ASSESMENT: PF: 1 CF: 2 TOT	AL: 2	
AVERAGE ANNUAL DAILY 800 (west), 1260 (east), (Ref		CONTRACTOR MAINTENANCE AREA (CMA): 28		

SUMMARY OF SITE INSTRUMENTATION:	INSPECTED BY:		
	Chris Gräpel (KCB)		
	Chris Morgan (KCB)		
None	Renato Macciotta (KCB)		
None	Roger Skirrow (AT)		
	Alex Frotten (AT)		
	Nicolas Ropchan (AT)		
LAST READING DATE: N/A			
	·		

PRIMARY SITE ISSUE: Gabion wall at the site had been toppling due to undermining.

APPROXIMATE DIMENSIONS: N/A. Previous failure had included approximately 17 m of gabion wall.

DATE OF ANY REMEDIAL ACTION: The gabion wall was repaired in 2018 with shotcrete and tie-back rock anchors. A new chain link fence and w-beam guardrail was erected.

ITEM	COND		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		Χ	Gravel road.		Х
Slope Movement		Х	Gabion wall repairs completed in 2018.	Х	
Erosion		Х	Repairs completed last year. None observed to date.	Х	
Seepage		Х	None observed		Х
Culvert Distress		Х			Х

## **COMMENTS**

Repair works completed in 2018. Visit the site every 2 years and prepare to remove site from GRMP in 4 years.

Photo 1 Completed gabion wall repairs. Photo taken facing north on May 7, 2019.



Photo 2 New guard rail barrier and chain link fence after completion of the gabion repairs. Photo taken facing northeast on May 7, 2019.



