

SOUTHERN REGION GEOHAZARD RISK ASSESMENT SITE INSPECTION FORM



SITE NUMBER AND NAME	HIGHWAY & KM:	PREVIOUS INSPECTION DATE		
S010A Archery Range	762:02, 10.026	INSPECTION DATE: April 30, 2018		
		June 14, 2016		
LEGAL DESCRIPTION	NAD 83 COORDINATES:	RISK ASSESMENT		
NE 33-21-4-W5	UTM Northing Easting	PF: 1		
	11 5633710 676840			
AVERAGE ANNUAL DAILY TR	RAFFIC:	Contractor Maintenance Area:		
800 (north), (Ref No. 65170)		27		

INSPECTED BY:		
Chris Gräpel (KCB)		
Peter Roy (KCB)		
Alex Frotten (AT)		
Roger Skirrow (AT)		
Maury Siddons (AT)		

PRIMARY SITE ISSUE: Monitoring landslide repairs affecting the highway embankment and underlying natural slope.


APPROXIMATE DIMENSIONS: Slide affecting highway was approximately 35 m long. Embankment slope of 2.5H:1V to 3H:1V, approximately 6 m high. Toe bulge located 15 m beyond toe of embankment slope on private land.

DATE OF ANY REMEDIAL ACTION: Highway improvements completed in Fall 2017. Work included reconstruction of the highway embankment with light weight fill and drainage in the embankment. Asphalt overlay and HTCB barrier installed on west shoulder.

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		Χ	Overlay completed in Fall 2017.	Х	
Slope Movement		Χ			Х
Erosion	Х		Vegetation yet to take on slopes. Erosion noted in the east ditch.	Х	
Seepage		Χ			Х
Culvert Distress		Χ			X

COMMENTS

The ditches were mulched but rolled erosion control product was not used. Ditch may erode with spring and early summer runoff when vegetation is not well established.



Time: 13:33:48 PM Date: August 08, 2018

Photo 1 Highway repair completed in 2017. HTCB installed on southbound lane shoulder. Photo taken facing northeast on April 30, 2018.



Photo 2 West embankment of highway. Photo taken facing northeast on April 30, 2018.



Photo 3 Drainage installed beneath highway. Rock placed at outlet of drain. Photo taken facing west on April 30, 2018.



Photo 4 East side of highway ditch. Some erosion noted. Rolled erosion control product not used on ditch bottom. Vegetation not established on slopes. Photo taken facing northeast on April 30, 2018.

