



Photo S10(C)-1 – June 2005 (upper left)
Cracking and settlement of the road surface as observed during the 2005 site inspection.



Photo S10(C)-2 – June 2007 (upper right)
Typical view facing north across the recent overlay at the site, as seen during the June 2007 site inspection. The approximate location of the culvert to the south of the overlay is shown.



Photo S10(C)-3 – June 2007 (lower left)
Closer view of the edge of the recent overlay, along the east shoulder of the road. The approximate location of the culvert to the south of the overlay is shown.



Photo S10(C)-4 – June 2007 (lower right)
Facing south along the west shoulder of the road. The culvert shown in Photos S10(C)-5 and 6 is just behind the two people standing in the ditch to the right of the road.