

Photo 1 Highway and bank above cut bank on secondary channel S45-I. Photo was taken facing west on May 29, 2017.



Photo 2 Downstream of eroded slope. No change in creek erosion towards road embankment in approximately 4 years. Photo was taken facing northeast May 29, 2017.



Photo 3 **Tree debris blocking river from entering creek. No change in tree debris from 2016 inspection. Some additional plant growth. Photo was taken facing southwest on May 29, 2017.**

