BRIDGE POSTING AND UTILITIES



1

Posting and Utilities Information

- Posting refers to Posted Loading or Posted Vertical Clearance
- Information is entered into TIMS BIS application at first inspection
- · On subsequent BIM reports
- · Inspectors verify information is correct
- · Inspectors revise if incorrect
- · Note and report changes in Posting information for system updating

Albertan

0

Responsibility for Posting

- All bridges on local roads are responsibility of Local Road Authority (County, MD, Town, Village, rtc)
 - passing by-laws
 - purchasing, installing and maintaining signage

Albertan

Vertical Clearance



- · On culvert Grade Separations and other various Major bridge forms
- · Mounted at midpoint over travel lanes
- · Advance warning in each direction
- Legal height in Alberta without a permit is 4.15m
- New grade separation structures are designed for 5.35m clearance

Albertan

2

3

Vertical Clearance

- · Inspection and Coding
 - look for signs in advance and on bridge
 - legible and visible
 - clearance values consistent
 - If signs are missing record as "No"
 - note direction and location if missing and notify RRA
 - look for new pavement or gravel
 - notify RRA if signs are incorrect or inconsistent



Albertan

5

Vertical Clearance Posting is Important!





Albertan

Vertical Clearance Posting is Important!





Albertan

Posted Loading - BIM Bulletin #8

BIM Advisory Bulletin # 8 - April 2021

Legal Loads on the Local Roads

On January 1, 2021, the Commercial Vehicle Dimension and Weight Regulation was amended. Part of the changes involved the removal of the previous weight restrictions for tri-drive and tidem axies on non-highway (Local Reads) readways. As a result, the legal CS3 truck load for Local Roads previously had 54 fornes rating will now have the same 63.5 tonnes rating as for the Provincial Highways.

Effective immediately, Table 5.1 of Bridge inspection and Maintenance System – inspection Manual (Version 4.0 – December 2020) will be replaced in its entirety with the following:

Truck Type	Local Roads	Provincial Highways 28 tonnes 49 tonnes		
Single (CS1)	28 tonnes			
Semi (CS2)	49 tonnes			
Truck Train (CS3)	63.5 tonnes	63.5 tonnes		

*previously 54 tonnes

in addition, the eleventh bullet point in Section 5.2.2 of Bridge inspection and Maintenance System – Inspection Manual (Version 4.0 – December 2020) is deleted and is replaced in its entirety, with the following:

"Iron Movekie Load or Design Load is shown, or CS3 husk back for Local Roads is less than SE Lonnes on the BMI happedies from and is not controlly posted, a seconmendation to see allowable load should be made in the Special Comments for Next Inspection field. For these bridges, the Responsible Road Authority should inflate appropriate action, to either confirms that the bridge is sufficient for a CS3 63.5 tones rating or the Responsible Road Authority will need to post the bridge to CS3 64 tones.

Albertan

6

D 0

Posted Loading

Bridges that cannot accommodate legal loads are posted Legal Loading on:

Local Roads


CS 1 28 tonnesCS 2 49 tonnes

- CS 3 63.5 tonnes

· Provincial Highways

CS 1 28 tonnesCS 2 49 tonnes

- CS 3 63.5 tonnes



Albertan

Posted Loading

- · Inspection and coding
 - compare Allowable Load to legal loads to determine if posting is required
 - loading values on sign consistent with "Allowable Loading" and "Required Load Posting" on report
 - note posting at the junctions of roads leading to bridge, in advance, and at the bridge structure
 - legible and visible
 - note missing or incorrect signs, report to responsible authority

Allowable Loa	d (t): Single	H 18 STRINGER		HS 32 STRINGER		CS3 48 STRINGER		> On Crit	
Design Loadin	gn Loading: HS15 -						> Primary Span		
				Posting Inf	ormation				
Required Load Posting (t)		Single	18	Semi		Truck Train		48	
Posted Loadin	g (t)		Single	10.0	Semi		Truck	Train	
Posted:	Lane	EB	At Junction (Y/N	No	In Advance (Y/	N) Yes	At Bridge (Y/N)		No
Posted:	Lane	WB	At Junction (Y/N	Yes	In Advance (Y/	N) No	At Bri	dge (Y/N)	Yes
Remarks	Located	Located on dead end road W/B. E/B signing is adequate. Posted at 10 T							

Albertan


8

Posted Loading | State | Stat



10 11

2--- 2



Hazard Markers

- Inspection and Coding
 - noting orientation and location (in line with bridge railing & 1200mm above deck top/wearing surface) except when required to be higher due to snow banks
 - note condition
 - If not installed because not required record "No" and "Not reg" in "Remarks" area
 - If some missing record as Yes or No? Make comments in "Remarks" area
 - If all missing record as "No" and make maintenance recommendation to install
 - problems notify responsible authority

Other Signs

13

- · Narrow Bridge, Speed Limit, Curve, Bump,
 - note condition, legibility
 - record type and location

Albertan

12

Utilities

	Utilities (Located at)		
Telephone	Gas		
Power	Municipal		
Others	Problem (Y/N)		
Remarks			

- · Utility owner responsible for maintenance or removal if requested by RRA
- · Note only those on or within 200 m of bridge or culvert
- · Check if utility
 - overloads bridge
 - interferes with maintenance or operations
 - hazard to public or bridge
 - unattractive appearance (corrosion, loose and sagging)
- · Installed only after review and approval of AT or LRA staff

Albertan

Utilities Proper Locations

- · Newer prestressed concrete bridges
 - Voids/ducts in curbs for Telephone and Power
- Reinforced concrete precast
 - clamp on curb fascia
- · Older pre-stressed concrete precast
 - in outside void of stringer
- · Should not interfere with bridge or culvert maintenance

Albertan

14 15

Dogo 1

Utilities Improper Attachments

- · Drilled into pre-stressed girders
- · Explosive fasteners in steel or concrete
- Welding or drilling on steel members or in culvert barrels
- · Oversize holes in timber
- · Failure to treat cut timber

Albertan

17

Utilities

- · Inspection and Coding
 - note location of power, phone, etc. within 200m (i.e. East ROW)
 - remark if hazardous, report to owner
 - look for improper installation
 - look for leaks in water, sewer or gas
 - check connections for safety
- · Notify RRA (AT or LRA) concerning problems or defects

Albertan

16

Culverts

- · Vertical clearance only if underpass
- No load posting
- Utilities typically not in culverts
- May have ducts in headwalls
- Record location of power, phone, etc. within 200m (i.e. West ROW)

Albertan

Major Bridges

- Local Road Authorities are responsible for signing of major bridges on Local Roads
- · Lack of signs
 - legal liability
 - damage bridges
 - damage / injury to public
- Report missing or incorrect Posted Loading signs to Bridge Manager & Bridge Preservation Specialist, or LRA as appropriate.

Albertan

18

