



Photo 1 Up hill general pavement cracks.



Photo 2 Mid-hill general pavement cracks.



Photo 3 Collection point at the toe of the slope.



Photo 4. Water ponding at the backslope manhole.