





Approach Road - Evaluation and Rating **Road Use** • Roads are used by: • Old people who may have reduced abilities Teenagers who just got licenses Immigrants who are still inexperienced Inattentive drivers Impaired drivers Drivers who speed Bad drivers • Drivers who are unfamiliar with the area Autos that have bald tires • Right or wrong, alignment handles them all. Coupled with abuse, success is not always guaranteed. Technical Standards Branch Class B Bridge Inspection Course Alberta.









Approach Road - Evaluation and Rating

Alignment

- Design speed is the posted legal speed for road plus 10 kph
- Evaluate by driving at the legal speed limit if safe to do so and if conditions permit.
- · Observe sight distances
- Note if bridge is superelevated
- Note presence of speed limit or other signs
 - Sharp curve
 - Bus stop ahead
 - indicates sight distance problem
 - Intersection ahead
 - indicates sight distance problem



Technical Standards Branch Class B Bridge Ipspection Course



Approach Road - Evaluation and Rating

Horizontal Alignment Defects

- Horizontal defects result in a reduction in speed to drive the road safely. They include:
- Reduced visibility trees, buildings, embankments
- Sharp corners
- ➤ Intersecting roads
- > Bridge is at beginning of curve
- > Bridge is offset from straight alignment
- Note if passing can still be done safely



Technical Standards Branch Class B Bridge Inspection Course



Approach Road - Evaluation and Rating

Horizontal Alignment Ratings

- Note presence of intersecting roads and record location on form (Field accesses do not affect rating).
 - Rate 7 or less depending on visibility, traffic volume and traffic type.
 - Rate may be 8 or 9 if no intersections for 1km
- If horizontal defect is cause of reduced speed, then rate:
 - 6 or more if driven safely at legal speed limit
 - 5 if can be driven safely and posted not more than 20 km/hr below legal speed limit
 - 4 or less if posted more than 20 km/hr below the legal speed limit
 - 4 or less if sharp or blind curves
 - 5 if Land Access bridge and appropriate warning signs are in place.



Technical Standards Branch Class B Bridge Inspection Course



Approach Road - Evaluation and Rating

Vertical Alignment Defects

- Vertical alignment defects result in a reduction in speed to drive the road safely. They include:
- Reduced visibility crests in road
- Steep grades (take into consideration road surface e.g. loose gravel)
- ➤ Adequate sight distance for stopping or passing
- ➤ Intersecting roads



Technical Standards Branch Class B Bridge Inspection Course



Approach Road - Evaluation and Rating

Vertical Alignment Rating

- Vertical alignment with a straight grade of 1% or less - rate 9
- If road can be driven safely at legal speed limit rate 6 or more
- If road can be safely driven and posted not more than 20 km/hr below legal rate 5
- Rate 4 or less if:
 - posted more than 20 km/hr below posted speed
 - sight distance is less than required
 - Steep grades, blind crest curves
- Rate 2 if combined effect of horizontal and vertical alignment is hazardous (e.g. very steep hill combined with sharp hair-pin curve)
- Rate 5 if Land Access bridge



Technical Standards Branch Class B Bridge Inspection Course



Approach Road - Evaluation and Rating


Alignment


- For land access structures:
 - Road services land only, not residential access
 - Local road standards do not apply
 - Consider suitability for traffic
- If adequate for intended use and appropriate warning signs are in place, the Horizontal and Vertical alignment ratings can be rated 5




Technical Standards Branch Class B Bridge Inspection Course







Approach Road - Evaluation and Rating **Approach Bump** • May be a symptom of - Settlement of the approach fill Instability of the fill (slumping) Undermining of fill by water Settlement of or damage to approach slab • Drive over at legal speed if safe – or at safest speed that conditions allow Observe traffic crossing structure • If no defects and smooth transition rate 9 • If bump is noticeable but tolerable - rate 5 If speed must be reduced - rate 4 or less • If hazardardous to traffic - rate 2 or less Technical Standards Branch Alberta Class B Bridge Inspection Course BIM



Guardrail - Culverts · Rating is not required Record the presence of guardrail by Yes or No • Provide comment if guardrail is on one shoulder only Guardrail that is too short or is otherwise ineffective - provide comment and maintenance recommendation Provide comment and maintenance recommendation if missing and is required for Note defects (e.g. - broken posts, damaged rails) and provide comment and maintenance recommendation • No indicates negualserailds Branch
Class B Bridge inspection Course BIM Transportation

Approach Road - Evaluation and Rating

Approach Road - Evaluation and Rating

Guardrails - Bridges

- Record the presence of guardrail by Yes or No
- Record the minimum length to the nearest meter
 - Explain if different lengths exist
- Maximum is 99 m
- · Record the type of termination
 - Common type is Turned Down, wing, Attenuator
- Based on current Standard Drawings record if the guardrail meets current standards (Yes/No)
 - Explain if No
 - Acceptable explanation is "Not thriebeam"
- Link to current Standard Drawings:
- http://www.transportation.alberta.ca/4855.ht m



Technical Standards Branch Class B Bridge Inspection Course



Approach Road - Evaluation and Rating

Guardrails - Bridges

- Inspect up to 45m from bridge
- Inspect all components of guardrail
 - Posts
 - Rail
 - Connections
 - Splices
 - Termination
- Rate according to condition only not standard
- Minor damage but still functional rate 5
- Missing bolts or improper laps 4 or less
- Damaged requires replacement rate 3 or less
- Damaged potential hazard rate 2 or less
- Rate "X" if no guardrail exists
 - If required, recommend action and explain



Technical Standards Branch Class B Bridge Inspection Course



