







View of silted up ditch at toe of valley slopes

Scarp of slide about 0.8 m from edge of pavement



Views looking south at scarp of slide





Looking north. Note cracks in lower left corner of photo.



Main scarp of slide. Scarp is about 4 m wide and 2 m high.
Note darker band at about mid-height which is a saturated sandy seam.



Steep scarps to the south of the main slide.
The area of instability extends for a width of about 14 m.



Looking south.



Looking south. Note cracking of slope.



Another view of the main scarp next to the highway.



Typical erosion along riverbank.











Another view of the ditch on the west side of the highway.