Piezometer and Standpipe Monitoring Summary

Location	PN#01-1A	SP01-1	SP01-2	Comments
GPS - Northing	5897869	5897916	5897961	
GPS - Easting	639710	639721	639720	
Piezometer Number	26544		-	
Stick - Up (m)	-	0.7	0.7	
Tip Depth (m)	10.70	12.93	14.90	
Ground Elevation (m)	599.84	595.63	590.83	
Date	Piezometric Reading (kPa)	Stand Pipe Reading (t.o.p.)		
May 23, 2001	69	14.92 ft	39.31 ft	
September 7, 2001	79	12.5 ft	25.1 ft	
June 4, 2002	79	7.89 ft	7.09 ft	
October 6, 2002	77	8.94 ft	14 ft	
May 25, 2003	76	6.44 ft	6.9 ft	
October 30, 2003	69	7.15 ft	7.55 ft	
May 7, 2004	72	14.24 ft	9 ft	
October 5, 2004	69	15.68 ft	10.5 ft	
May 12, 2005	69	16.68 ft	11.5 ft	
September 29, 2005	70	2.7 m	3 m	
May 29, 2006	69	2.6 m	3.1 m	
October 6, 2006	78	3.45 m	3.26 m	
May 15, 2007	79	2.8 m	3.3 m	
October 2, 2007	79	4.8 m	3.3 m	
May 23, 2008	73	2.73 m	3.26 m	
September 26, 2008	76	5.19 m	3.54 m	
May 20, 2009	69	5.13 m	3.73 m	
October 20, 2009	73	5.18 m	3.76 m	
May 10, 2010	68	5.98 m	4.97 m	
October 5, 2010	68	2.47 m	3.45 m	
May 17, 2011	69	3.05 m	3.30 m	
October 5, 2011	(F)	3.36 m	-	PN01-1A and SP01-2 have both been destroyed from construction activities