



PHOTO 1: Cracks re-opening through Fall 2005 ACP patch.



PHOTO 2: Stretch cracks at west end of slide.



PHOTO 3: Patches over 2004 scarp.



PHOTO 4: Uphill view of slope and creek.