



Photo 1 - View of active slide scarp across the roadway surface, facing west.



Photo 2 - Cracks reopening through Fall 2005 ACP patch.





Photo 3 - View of Highway 690 facing west, showing a dip in the pavement.



Photo 4 - View of creek facing east.





Photo 5 - View of creek facing west.



Photo 6 - Uphill view of slope and creek.