



PHOTO 1 - View of Highway 690 facing west, showing a dip in the pavement.



PHOTO 2 - View of slide scarp reaching the north shoulder and turning towards the east, penetrating again into the westbound lane.



PHOTO 3 - View of active slide scarp across the roadway surface, facing west.



PHOTO 4 - View of active slide scarp across the roadway surface, reaching the south shoulder, facing southwest.



PHOTO 5 - View of extended and widened cracks facing west.



PHOTO 6 - View of Highway 690 facing east, showing a dip in the pavement.



PHOTO 7 - View of creek facing west.



PHOTO 8 - View of creek facing east.