



PHOTO 1: Looking west along Hwy 690:02 at the active backscarp location



PHOTO 2: Looking east along Hwy 690:02 at the active backscarp location



PHOTO 3: Subdued Scarp near the Toe of the Side Slope



PHOTO 4: Creek Bed at the Toe of the Slope