

LANDSLIDE RISK ASSESSMENT
SOUTHERN REGION

SITE S2: PRIDDIS

LEGAL LOCATION: LSD 1-34-22-4 W5M

REFERENCE LOCATION ALONG HIGHWAY: Approximately 11 km west of Priddis turn-off.
Approximately 10 km southeast of Bragg Creek (measured along road).

UTM COORDINATES: 5642400 N 678200 E (NAD27)
NTS Map Sheet 82 J/16 (Priddis)

AI FILE: H22:14

AI PLAN & PROFILE:

Date of Initial Observation: unknown

Date of Last Inspection: Inspected May 2006
Instruments read October 2006

Instruments Installed: Unknown date – 4 slope inclinometers
November, 1992 – 6 slope inclinometers, 4 pneumatic piezometers
Unknown date – 1 slope inclinometer
February 2001 – 2 slope inclinometers (AMEC)
- 1 settlement gauge

Instruments Operational: 4 slope inclinometers
3 pneumatic piezometers

Risk Assessment: $PF(9) * CF(5) = 45$
(reduced from $11 * 5 = 55$ in June 2002)

Last updated by: AMEC, November 2005

Comments: